

INSPECTION REPORT

CATERPILLAR 730C2

The Caterpillar 730C2 is a robust articulated dumper with a powerful Caterpillar C13 engine generating 276 kW. This model features a 6x6 drive and an EROPS cabin, designed for superior performance in tough environments. With a large tailgate, backup camera, and retarder, it ensures efficient and safe operation. Additional features include air conditioning, backup alarm, central lubrication, and a beacon. The vehicle is equipped with GOODYEAR 750/65R25 tires at 70% tread. Certified hours and a condition report confirm its very good and clean state.



Specifications

Year	2016
Hours	10495
Weight	24100 kg
Serial number	CAT0730CV2T400167
Reference	211832

Features

Engine	Caterpillar
Engine model	C13
Engine power	276 kW
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Tailgate	Big tailgate
Backup camera	✓
Backup alarm	✓
Beacon	✓
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Transmission guard	★ ★ ★ ★ ★

Engine Details And Condition

Engine number	T4F05359
Air cleaner	New
Anti-freeze level °C	-36°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★ ★ ★ ★ ★
Muffler	★ ★ ★ ★ ★
Exhaust stack	★ ★ ★ ★ ★
Engine supports	★ ★ ★ ★ ★
Hoses	★ ★ ★ ★ ★
Good cold start	Yes
Engine power	★ ★ ★ ★ ★
Blow by	★ ★ ★ ★ ★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★ ★ ★ ★ ★
Fan	★ ★ ★ ★ ★
Radiator	★ ★ ★ ★ ★

Operator Station

Hourmeter	Working, hours certified by Caterpillar
Total kilometers	55070 km
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Small crack no need to repair
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

Frame

Play front suspension frame	★★★★★
Play middle suspension frame	★★★★★
Play rear suspension frame	★★★★★
Play articulation point	★★★★★
Shock absorbers articulation point	★★★★★
Play body tipping pin	★★★★★
Bearings tipping cylinders	★★★★★
Shock absorbers body	★★★★★
Play rear equalizer	★★★★★
Shock absorbers equalizer	★★★★★
Cracks or welds	No

Body

Condition outside body	★★★★★
Body plates	★★★★★
Condition tailgate	★★★★★
Cracks or welds	No

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

Brake

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★

Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transfer gear box oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes
Oil level middle axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level middle left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level middle right final drive ok	Yes
Oil level front right final drive ok	Yes
Drive chain leaks	No

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

Safety Items

Backup alarm	Working
Backup camera	Working
Seat belt	Available
Horn	Working
Beacon	Working

Tyres

Front Left

Tread dept in mm 32mm
Percentage life remaining 70%

Middle Left

Tread dept in mm 31mm
Percentage life remaining 70%

Rear Left

Tread dept in mm 27mm
Percentage life remaining 60%

Rear Right

Tread dept in mm 31mm
Percentage life remaining 70%

Middle Right

Tread dept in mm 31mm
Percentage life remaining 70%

Front Right

Tread dept in mm 33mm
Percentage life remaining 70%



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)



sales@smitma.com



[+31 \(0\) 77 3999 840](https://wa.me/31773999840)