



## **CATERPILLAR 140K**

#### **Description**

Caterpillar 140K, Engine and model Caterpillar C7, 143 kW, Air conditioning, 17.5R25, Push block, Ripper, 6x4, High profile erops cabin, Auto shift, Hydraulic tip control, Width of the center blade 4.27m, Blade lift accumulators, Differential unlock, Hours certified by Caterpillar, In very good and clean condition.



Year	2018
Hours	3867
Weight	15.000 kg*
Serial number	CAT0140KAJPA04783
Reference	205458

**Download photos** 









CONTACT US:

SALES@SMITMA.COM +31(0)773999840



# **INSPECTION REPORT**

#### **FEATURES**

Engine and model	Caterpillar C7
Engine power in kW	143 kW
Push block	✓
Ripper	✓
Cabin	High profile erops cabin
Hydraulic tip control	✓
Width of the center blade	4.27m
Overall condition	In very good and clean condition.

## **GENERAL APPEARANCE**

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	****
Decals	****
Bonnet	****
Engine cover doors	****
Battery box	****
Radiator grill	****
Steps/ladders	****
Grab irons Grab irons	****
Cabin	****
Transmission guard	****
Pre-cleaner bowl	****
Sheet metal	****
Cracks or welds	No

# **ENGINE DETAILS AND CONDITION**

Engine number	TX706916
Arrangement number	5115381
Air cleaner	Clean
Anti-freeze level °C	-36°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes

Exhaust manifold	****
Muffler	****
Exhaust stack	****
Engine supports	****
Hoses	****
Good cold start	Yes
Engine power	****
Blow by	****
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	****
Fan	****
Radiator	****

## **OPERATOR STATION**

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	****
Warning	No Warnings Available
Mirrors	Not Broken
Cabin glass	Not broken
Display	****
Windshield wipers	Few don't work
Interior lights	Working
Cabin floor	****
Interior roof	****
Seat	****
Steering column	****

## **STEERING**

Articulate cylinder leaking	No
Play articulate cylinder	****
Play articulating point	****

Wheel lean cylinder leaking	No
Play wheel lean cylinder	****
Steering cylinders leaking	No
Play steering cylinders	****
Play king pin front axle	****
Steering frame	****
Steering pump	****
Steering operating condition	****
BLADE	
Circle A frame	****
Play circle A frame	****
Circle frame	****
Play circle frame	****
Cutting edge	****
Ring gear	****
Moldboard skin	****
RIPPER	
Play ripper	****
Lifting cylinder leaking	No
Ripper frame	****
Number of scarifier shanks	4
Number of ripper shanks	3
HYDRAULICS	
Hydraulic oil level ok	Yes
Blade lift accumulators	2
Hydraulic lines and fittings	****
Hydraulic tank/sight glass and cap	****
Play lift cylinder	****
Lift cylinders leaking	No
Play side shift cylinder	****
Side shift cylinder leaking	No
Play circle shift cylinder	****
Circle shift cylinder leaking	No
Play tip cylinder	****
Tip cylinder leaking	No
Hydraulic valves leaking	No

Circle drive leaking	No
Operating condition hydraulics	****
Noise hydraulic pump normal	Ye
BRAKE	
Brakelines	****
Service brake operation	****
Parking brake operation	****
Compressor	****
Brake pedal	****
TRANSMISSION	
Transmission controls	****
Transmission noisy	N
Leaks	N
Transmission oil level ok	Ye
Transmission fully operational in all gears	Ye
forward and reverse	
DRIVE CHAIN/TANDEMS	
Differential lock/unlock working	Ye
Tandem housing	****
Left tandem leaking	N
Left tandem oil level ok	Ye
Right tandem leaking	N
Right tandem oil level ok	Ye
Wheel bolts and rims	****
ELECTRICAL, STARTING AND CHARGING SYSTEM	1
Alternator functioning	Ye
Wiring	****
Batteries	****
Starter	****
Head lights working	Ye
	Ye
Tail lights working	
Signal lights working	Ye

	Workin
Seat belt	Availabl
Horn	Workin
Parking Brake	Workin
YRES	
FRONT LEFT TYRES	
Tread dept in mm	20mm
Percentage life remaining	70%
MIDDLE LEFT TYRES	
Tread dept in mm	10mm
Percentage life remaining	30%
REAR LEFT TYRES	
Tread dept in mm	9mm
Percentage life remaining	30%
REAR RIGHT TYRES	
Tread dept in mm	10mm
Percentage life remaining	30%
MIDDLE RIGHT TYRES	
Tread dept in mm	9mm
Percentage life remaining	30%
FRONT RIGHT TYRES	
Tread dept in mm	20mm
Percentage life remaining	70%
	USTED
New/Excellent Very good Good Fair Poor ★★★★★ ★★★★ ★★★★ ★★★★ ★★★★ ★★★★★	SINCE
	1960