

Evaluation Mobile Material Handler		www.mevas.net	 MEVAS
Customer/Location:	Prima / Hardenberg	vers 12-2024	
Date:	15.12.2025		
Machine / type:	Terex Fuchs MHL360	Hour reading:	7203
Serial No.:	3601100913	Year:	2011
Inspector:	B. Hecker	stick length:	7,80 m
CE <input checked="" type="checkbox"/> EPA <input type="checkbox"/> A/C <input checked="" type="checkbox"/> generator <input type="checkbox"/>		industrial boom <input checked="" type="checkbox"/>	industrial stick <input checked="" type="checkbox"/>
stabilizer blade <input type="checkbox"/> auto lube <input checked="" type="checkbox"/> stabilizers <input checked="" type="checkbox"/>		auxiliary lines <input checked="" type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>
cab		cab door	good
seat, arm rests	worn and loose cushion	windows, mirrors	good
switches, levers	rubber knobs missing	wipers, washer	good
gauges, warn lights	good	floor mat, covers	good
aircon / heater	good	cab structure	good
engine			
leaks & seals	no leaks seen	Serial No.	21044464
oil condition & level	good	cooling system	good
exhaust, muffler	good	blow by	minor
smoke	normal	belts & filters	good
DPF/DEF status	N/A	coolant condition	good
visual inspection exterior		sheet metal	good
chassis	good	bumpers	good
engine hood	good	outriggers/blade	good
stairs, hand rails	cracked welding on left top rail	lights, batteries	good
boom	good	paintwork	some rusty components
stick	good	rims, wheel nuts	good
hydraulics & drive train		boom cylinders	good
hoses & lines	good	stick cylinder	drift noted
pump and valve bloc	good	bucket cylinder	N/A
transmission gear	good	outr/blade cylinders	leaking
swivel joint	good	universal joints	good
functional test		swing drive & brake	good
pins boom	good	pump noises	good
pins stick	good	slew ring play	1mm play
generator, cab raiser	good	brakes	good
pins bucket & linkage	no	drive operation	good
tools		rotation test	good
grapple size, kind	orange peel grapple	hoses/connectors	leaking
arm condition	good	pins & bushings	good, safety pins missing
tires	mm (%) remaining life	size:	12.00 - 24
front right	20/0%	twin / mono:	twin
front left	5/0%	spacer rings:	<input checked="" type="checkbox"/>
rear right	40/40%	cuts:	some chunks
rear left	40/20%	solid:	<input checked="" type="checkbox"/>
problems, details:	<p>side door locks not working, handle on side cover cracked, left front top step is loose</p> <p>equipped with pressurized cab - not working</p> <p>can bus errors CR2016 and CR0303 shown on display</p>		
<p><i>The machine is in general good condition. Some smaller repairs and replacements required.</i></p>			
dimensions for transport L x W x H in meter:	14,60 m x 3,00 m x 3,50 m		