

Evaluation Mobile Material Handler		www.mevas.net	 <small>© 2022 MEVAS Liability for hidden defects excluded.</small>
Customer/Location:	Prima / Hardenberg	vers 12-2024	
Date:	16.12.2025		
Machine / type:	Terex Fuchs MHL335	Hour reading:	14282
Serial No.:	335010 / 0277	Year:	2012
Inspector:	B. Hecker	stick length:	4,0 m
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/>	A/C <input checked="" type="checkbox"/> generator <input type="checkbox"/>	industrial boom <input checked="" type="checkbox"/>	industrial stick <input type="checkbox"/>
stabilizer blade <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/> stabilizers <input type="checkbox"/>	auxiliary lines <input checked="" type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>
cab		cab door	good
seat, arm rests	cover on head rest loose	windows, mirrors	good
switches, levers	good	wipers, washer	good
gauges, warn lights	good	floor mat, covers	worn
aircon / heater	good	cab structure	good
engine			
leaks & seals	no leaks seen	Serial No.	11199032
oil condition & level	good	cooling system	radiator cap broken
exhaust, muffler	good	blow by	minor
smoke	normal	belts & filters	good
DPF/DEF status	N/A	coolant condition	good
visual inspection exterior		sheet metal	cooler mesh bent
chassis	good	bumpers	good
engine hood	good	outriggers/blade	good
stairs, hand rails	some steps bent	lights, batteries	batteries broken
boom	good	paintwork	chipped and faded
stick	good	rims, wheel nuts	good
hydraulics & drive train		boom cylinders	good
hoses & lines	1)	stick cylinder	good
pump and valve bloc	good	bucket cylinder	scratches on chrome rod
transmission gear	good	outr/blade cylinders	good
swivel joint	good	universal joints	good
functional test		swing drive & brake	good
pins boom	minor play	pump noises	normal
pins stick	minor play	slew ring play	1,0 mm
generator, cab raiser	good	brakes	good
pins bucket & linkage	minor play	drive operation	good
tools		rotation test	no
grapple size, kind	no	hoses/connectors	no
arm condition	no	pins & bushings	no
tires	mm (%) remaining life	size:	10.00 - 20
front right	50%	twin / mono:	twin
front left	50%	spacer rings:	<input checked="" type="checkbox"/>
rear right	50%	cuts:	cuts, shunks missing
rear left	50%	solid:	<input checked="" type="checkbox"/>
problems, details:	<p>1) some chafed and porous hoses, some lines leaking on the lower frame</p> <p>fuel tank open - looks like a line missing</p> <p>reverse cam not working</p> <p>equipped with pressurized cab and Verachtert quick coupler</p>		
<p><i>The machine is in general good condition. Smaller repairs and replacements recommended.</i></p>			
dimensions for transport L x W x H in meter:	10,00 m x 2,80 m x 3,30 m		