

<b>Evaluation Wheel Loader</b>		<a href="http://www.mevas.net">www.mevas.net</a>			
Customer:	<i>Prima</i>	vers 12-24			
Date:	<i>17.12.2025</i>				
Machine / type:	<i>Komatsu WA475-10EO</i>	location:	<i>Hardenberg</i>		
Serial No.:	<i>H47128</i>	Hour reading:	<i>7746</i>		
Inspector:	<i>B. Hecker</i>	Year:	<i>2021</i>		
CE <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/>	EPA <input type="checkbox"/> Auto-Greaser <input checked="" type="checkbox"/>	Hydrostat <input checked="" type="checkbox"/>	quick coupler <input checked="" type="checkbox"/>		
3rd valve <input checked="" type="checkbox"/>	supplemental steering <input checked="" type="checkbox"/>	weigh load <input type="checkbox"/>	Parts book <input type="checkbox"/> Op-Manual <input type="checkbox"/>		
<b>cab</b>		cab door	<i>good</i>		
seat, arm rests	<i>compressor not working</i>	windows, mirrors	<i>good</i>		
switches, levers	<i>good</i>	wipers, washer	<i>good</i>		
gauges & lamps	<i>good</i>	floor mat	<i>good</i>		
aircon / heater	<i>good</i>	cab structure	<i>good</i>		
<b>engine</b>					
leaks & seals	<i>no leaks seen</i>	Serial No.	<i>867317</i>		
oil condition & level	<i>good</i>	DPF&DEF status	<i>good</i>		
exhaust, muffler	<i>good</i>	cooling system	<i>good</i>		
smoke	<i>normal</i>	belts & filters	<i>good</i>		
blow by	<i>minor</i>	coolant condition	<i>good</i>		
<b>exterior</b>		counterweight	<i>good</i>		
chassis & lift arm	<i>good</i>	fenders	<i>two fenders bent</i>		
engine hood	<i>good</i>	lights, batteries	<i>good</i>		
stairs, hand rails	<i>good</i>	paintwork	<i>good</i>		
<b>power train</b>		rims, wheel nuts	<i>good</i>		
axles/differentials	<i>good</i>	universal joints	<i>good</i>		
gearbox	<i>good</i>	transfer gear	<i>good</i>		
power train	<i>good</i>	transm. noises	<i>good</i>		
<b>hydraulics</b>		steering cylinders	<i>good</i>		
hoses & lines	<i>good</i>	pumps & valves	<i>good</i>		
lift & tilt cylinders	<i>good</i>	steering orbital	<i>good</i>		
<b>functional test</b>	full bucket lift in seconds:		<i>6,5 sec.</i>		
steering	<i>good</i>	articulation play	<i>good</i>		
transmission test	<i>good</i>	loader pins	<i>good</i>		
stall test	<i>hydrostatic drive</i>	electric system	<i>good</i>		
brake / park brake	<i>good</i>	suppl. steering	<i>good</i>		
<b>bucket</b>		width / capacity	<i>3,15 m</i>		
edges / teeth	<i>good</i>	side condition	<i>good</i>		
bottom	<i>good</i>	quick coupler	<i>good</i>		
<b>tires</b>	<b>mm (%) good</b>	<b>size, brand, comments</b>			
front right	<i>25%</i>	<i>26,5 R25 Bridgestone</i>			
front left	<i>15%</i>	<i>26,5 R25 Bridgestone</i>			
rear right	<i>10%</i>	<i>26,5 R25 Bridgestone</i>			
rear left	<i>25%</i>	<i>26,5 R25 Bridgestone</i>			
<b>problems, details:</b>	<i>machine equipped with pressurized cab</i>				
	<i>guard underneath the transmission is missing</i>				
<i>The machine is in general good condition. No major problems found.</i>					
transport dimensions L x W x H in meter:	<i>8,50 m x 3,15 m x 3,60 m</i>				