

INSPECTION REPORT

AMMANN ASC130D

The Ammann ASC130D is a self-propelled roller powered by a Cummins QSB 4.5 engine with 119 kW. This 2007 model includes an EROPS cabin, EPA and CE certifications, and is equipped with an AM/FM radio. The machine weighs 12,630 kg and has dimensions of 5.55 x 2.45 x 3.10m. It has genuine hours and is in good, clean condition, ideal for heavy-duty applications.



Specifications

Year	2007
Hours	6053
Weight	12.630 kg*
Serial number	1072280051
Reference	213248

Features

Engine brand	Cummins
Engine model	QSB 4.5
Engine power in kW	119kW
EPA	✓
CE	✓
Tyre size	23.1-26
Hours	Genuine hours
Overall condition	In good and clean condition.

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★

Engine Details And Condition

EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-22°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

Safety Items

Seat belt	Available
Horn	Working
Parking brake	Working

Operator Station

Hourmeter	Working
Heater	Working
Gauges	Working
Switches	★★★★☆
Mirrors	Not broken
Cabin glass	Small crack, no need to repair
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆

Drum

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Leakages	No
Drum oil level ok	Yes
Vibration	High and low vibration frequency working
Drum measured in mm	22mm

Steering

Articulate cylinder leaking	No
Play articulate cylinder	★★★★☆
Play articulating point	★★★★☆

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

Drive Chain

Oil level rear axle ok	Yes
Rear axle leakages	No
Wheel bolts and rims	★★★★☆
Travel motors	★★★★☆
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Few lights don't work


Tyres

Rear Left Tyres


Tread dept in mm	8mm
Percentage life remaining	40%
Retreaded	Yes

Rear Right Tyres

Tread dept in mm	8mm
Percentage life remaining	40%
Retreaded	Yes

 [+31 \(0\) 77 3999 840](tel:+31(0)773999840)

 sales@smitma.com

 [+31 \(0\) 77 3999 840](tel:+31(0)773999840)