


Evaluation Wheel Loader		www.mevas.net	
Customer:	<i>Prima Equipment</i>	vers 01-22	
Date:	<i>09.12.2025</i>		
Machine / type:	<i>Hyundai HL980XT</i>	location:	<i>Hardenberg, NL</i>
Serial No.:	<i>HHKHW800LL0000197</i>	Hour reading:	<i>11431</i>
Inspector:	<i>Andras</i>	Year:	<i>2020</i>
CE <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/>	EPA <input type="checkbox"/> Auto-Greaser <input checked="" type="checkbox"/>	Hydrostat <input type="checkbox"/>	quick coupler <input type="checkbox"/>
3rd valve <input type="checkbox"/>	supplemental steering <input checked="" type="checkbox"/>	weigh load <input checked="" type="checkbox"/>	Parts book <input type="checkbox"/> Op-Manual <input type="checkbox"/>
cab		cab door	<i>Good</i>
seat, arm rests	<i>Good</i>	windows, mirrors	<i>Good</i>
switches, levers	<i>Good</i>	wipers, washer	<i>Good</i>
gauges & lamps	<i>Good</i>	floor mat	<i>Good</i>
aircon / heater	<i>Good / Good</i>	cab structure	<i>Good</i>
engine	<i>Scania DC13 (280 kW)</i>	Serial No.	<i>No legible label found</i>
leaks & seals	<i>residue on valve cover</i>	cooling system	<i>Good</i>
oil condition & level	<i>Good</i>	blow by	<i>Minor</i>
exhaust, muffler	<i>Good</i>	belts & filters	<i>Good</i>
smoke	<i>Normal</i>	coolant condition	<i>Good</i>
exterior		counterweight	<i>Good - scratched corners</i>
chassis & lift arm	<i>Good</i>	fenders	<i>Dents (1)</i>
engine hood	<i>Good</i>	lights, batteries	<i>Good</i>
stairs, hand rails	<i>Good</i>	paintwork	<i>Good</i>
power train		rims, wheel nuts	<i>Good</i>
axles/differentials	<i>Good</i>	universal joints	<i>Good</i>
gearbox	<i>Good</i>	transfer gear	<i>Good</i>
power train	<i>Good</i>	transm. noises	<i>Normal</i>
hydraulics		steering cylinders	<i>Good</i>
hoses & lines	<i>Good</i>	pumps & valves	<i>Good</i>
lift & tilt cylinders	<i>Good</i>	steering orbital	<i>Good</i>
functional test	full bucket lift in seconds:		
steering	<i>Good</i>	articulation play	<i>Good</i>
transmission test	<i>Good</i>	loader pins	<i>Good</i>
stall test	<i>Good</i>	electric system	<i>Good</i>
brake / park brake	<i>Good</i>	supplem. steering	<i>Good</i>
bucket		width / capacity	<i>3,20m / 6,1m³</i>
edges / teeth	<i>edge worn</i>	side condition	<i>Good</i>
bottom	<i>Good</i>	quick coupler	<i>N/A</i>
tires	mm (%) good	size, brand, comments	
front right	<i>36mm (60%)</i>	<i>All Triangle TB516 - 29.5R25 - semi-new</i>	
front left	<i>36mm (60%)</i>		
rear right	<i>36mm (60%)</i>		
rear left	<i>36mm (60%)</i>		
problems, details: <i>Equipped with all-round view cameras and AdBlue system.</i>			
<i>(1) LHS rear fender damaged (pics 38-39). RHS fenders with damaged plastic parts (pics 40-41).</i>			
<i>Active engine error codes: 5543 FMI 13 and 5543 FMI:7 - both about exhaust brake actuator failure.</i>			
<i>The machine is in good condition and ready to work.</i>			
<i>Some body work recommended. Scheduled maintainance and error codes service required.</i>			
transport dimensions L x W x H in meter:		<i>10 x 3,2 x 3,9</i>	