

VOLVO A35E FS

Description

Volvo A35E FS, Engine Volvo, D12DACE3, 309 kW, CE, Air conditioning, 6x6, Erops cabin, 26.5R25 Bridgestone , Retarder, Big tailgate, Body extensions, Backup camera, In good and clean condition.



Year	2008
Hours	15899
Weight	28.500 kg
Serial number	VCE0A35EC00010575
Reference	207964

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine	Volvo
Engine model	D12DACE3
Engine power	309 kW
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Tailgate	Big tailgate
Backup camera	✓
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Transmission guard	★ ★ ★ ★ ★
Pre-cleaner bowl	★ ★ ★ ★ ★

ENGINE DETAILS AND CONDITION

Engine number	321267
Air cleaner	Clean
Anti-freeze level °C	-35°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes

Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Small crack no need to repair
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

FRAME

Play front suspension frame	★★★★★
-----------------------------	-------

Play middle suspension frame	★★★★★
Play rear suspension frame	★★★★★
Play articulation point	★★★★★
Shock absorbers articulation point	★★★★★
Play body tipping pin	★★★★★
Bearings tipping cylinders	★★★★★
Shock absorbers body	★★★★★
Play rear equalizer	★★★★★
Shock absorbers equalizer	★★★★★
Cracks or welds	No

BODY

Condition outside body	★★★★★
Body plates	★★★★★
Condition tailgate	★★★★★
Cracks or welds	Yes

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transfer gear box oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes

Oil level middle axle ok	Yes
Oil level rear axle ok	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights working	No
Additional work lights working	Few lights don't work

SAFETY ITEMS

Backup camera	Not working
Seat belt	Available
Horn	Working

TYRES

FRONT LEFT	
Tread dept in mm	10mm
Percentage life remaining	20%
MIDDLE LEFT	
Tread dept in mm	20mm
Percentage life remaining	30%
REAR LEFT	
Tread dept in mm	13mm
Percentage life remaining	20%
REAR RIGHT	
Tread dept in mm	14mm
Percentage life remaining	20%
MIDDLE RIGHT	
Tread dept in mm	16mm
Percentage life remaining	30%
FRONT RIGHT	

Tread dept in mm	14mm
Percentage life remaining	20%

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------

Copyright Smilma BV

