


Evaluation Mobile Material Handler		www.mevas.net	
Customer/Location:	<i>Prima / Hardenberg</i>	vers 12-2024	
Date:	<i>15.12.2025</i>		
Machine / type:	<i>Terex Fuchs MHL350</i>		
Serial No.:	<i>3502101201</i>	Hour reading:	<i>11479</i>
Inspector:	<i>B. Hecker</i>	Year:	<i>2006</i>
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/>	A/C <input checked="" type="checkbox"/> generator <input type="checkbox"/>	stick length:	<i>6,00 m</i>
stabilizer blade <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/> stabilizers <input checked="" type="checkbox"/>	industrial boom <input checked="" type="checkbox"/>	industrial stick <input checked="" type="checkbox"/>
cab		auxiliary lines <input checked="" type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>
seat, arm rests	<i>good</i>	cab door	<i>good</i>
switches, levers	<i>good</i>	windows, mirrors	<i>good</i>
gauges, warn lights	<i>good</i>	wipers, washer	<i>good</i>
aircon / heater	<i>good</i>	floor mat, covers	<i>good</i>
engine		cab structure	<i>good</i>
leaks & seals	<i>good</i>	Serial No.	<i>10180197</i>
oil condition & level	<i>oil level too high</i>	cooling system	<i>good</i>
exhaust, muffler	<i>good</i>	blow by	<i>minor</i>
smoke	<i>good</i>	belts & filters	<i>good</i>
DPF/DEF status	<i>N/A</i>	coolant condition	<i>low level</i>
visual inspection exterior		sheet metal	<i>good</i>
chassis	<i>good</i>	bumpers	<i>good</i>
engine hood	<i>good</i>	outriggers/blade	<i>good</i>
stairs, hand rails	<i>good</i>	lights, batteries	<i>good</i>
boom	<i>good</i>	paintwork	<i>small scratches</i>
stick	<i>good</i>	rims, wheel nuts	<i>good</i>
hydraulics & drive train		boom cylinders	<i>good</i>
hoses & lines	<i>some porous and leaking hoses</i>	stick cylinder	<i>good</i>
pump and valve bloc	<i>good</i>	bucket cylinder	<i>N/A</i>
transmission gear	<i>good</i>	outr/blade cylinders	<i>good</i>
swivel joint	<i>good</i>	universal joints	<i>good</i>
functional test		swing drive & brake	<i>good</i>
pins boom	<i>good</i>	pump noises	<i>normal</i>
pins stick	<i>good</i>	slew ring play	<i>1,0 mm play</i>
generator, cab raiser	<i>good</i>	brakes	<i>good</i>
pins bucket & linkage	<i>N/A</i>	drive operation	<i>good</i>
tools		rotation test	<i>N/A</i>
grapple size, kind	<i>N/A</i>	hoses/connectors	<i>N/A</i>
arm condition	<i>N/A</i>	pins & bushings	<i>N/A</i>
tires	mm (%) remaining life	size:	<i>12.00 - 20</i>
front right	<i>60%</i>	twin / mono:	<i>twin</i>
front left	<i>60%</i>	spacer rings:	<input checked="" type="checkbox"/>
rear right	<i>60%</i>	cuts:	<i>some cuts</i>
rear left	<i>60%</i>	solid:	<input checked="" type="checkbox"/>
problems, details:			
<i>The machine is in general good condition according to the age and hour level.</i>			
<i>Some smaller replacements recommended.</i>			

dimensions for transport L x W x H in meter:	<i>12.00 m x 3,00 m x 3,40 m</i>
--	----------------------------------