

<b>Evaluation Wheel Excavator</b>		<a href="http://www.mevas.net">www.mevas.net</a>		
Customer/Location:	<i>Prima / Hardenberg</i>	vers 12-2024		
Date:	<i>16.12.2025</i>			
Machine / type:	<i>Hyundai HW140</i>	Hour reading:	<i>10449</i>	
Serial No.:	<i>HHKHK402PH0000236</i>	Year:	<i>2018</i>	
Inspector:	<i>B. Hecker</i>	stick length:	<i>2,50 m</i>	
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/>	A/C <input checked="" type="checkbox"/> stick check valve <input checked="" type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	quick coupler <input checked="" type="checkbox"/> DPF <input checked="" type="checkbox"/>	
mono-boom <input type="checkbox"/>	boom variable <input type="checkbox"/>	hammer lines <input type="checkbox"/>	lines for grapple / shear <input type="checkbox"/>	
<b>cab</b>				
seat, arm rests	<i>good</i>	cab door	<i>good</i>	
switches, levers	<i>good</i>	windows & mirrors	<i>good</i>	
gauges & warn lights	<i>good</i>	wipers, washer	<i>good</i>	
aircon / heater	<i>good</i>	floor mat & pedals	<i>good</i>	
		cab structure	<i>good</i>	
<b>engine</b>				
leaks & seals	<i>no leaks seen</i>	Serial No.	<i>22259995</i>	
oil condition & level	<i>good</i>	cooling system	<i>one radiator leaking</i>	
exhaust, muffler	<i>good</i>	blow by	<i>minor</i>	
smoke	<i>normal</i>	belts & filters	<i>good</i>	
DPF/DEF status	<i>good</i>	coolant condition	<i>good</i>	
<b>visual inspection exterior</b>				
chassis & carbody	<i>good</i>	counterweight	<i>good</i>	
side doors	<i>slight dents</i>	bumpers & covers	<i>good</i>	
stairs, hand rails	<i>good</i>	outriggers & blade	<i>LHS front cover missing</i>	
boom	<i>good</i>	lights, batteries	<i>RHS indicator broken</i>	
stick	<i>good</i>	paintwork	<i>good</i>	
		rims, wheel nuts	<i>good</i>	
<b>hydraulics &amp; drive train</b>				
hoses & lines	<i>good</i>	boom cylinders	<i>good</i>	
pump & valve bloc	<i>good</i>	stick cylinder	<i>good</i>	
transmission gear	<i>good</i>	bucket cylinder	<i>good</i>	
axles	<i>good</i>	outr/blade cylinders	<i>good</i>	
swivel joint	<i>good</i>	universal joints	<i>good</i>	
<b>functional test</b>				
pins boom	<i>minor play</i>	suspension lock	<i>good</i>	
pins stick	<i>minor play</i>	pump noises	<i>normal</i>	
pins bucket	<i>minor play</i>	slew ring play	<i>1,5mm play</i>	
boom self drift	<i>good</i>	brake & park brake	<i>good</i>	
swing drive/brake	<i>good</i>	electric system	<i>good</i>	
		drive operation	<i>good</i>	
<b>tools</b>				
bucket dimension	<i>1,2m GP bucket</i>	additional bucket	<i>N/A</i>	
bucket condition	<i>good</i>	coupler brand	<i>Verachttert CW20-H</i>	
		coupler condition	<i>good</i>	
<b>tires</b>				
	<b>mm (%) remaining life</b>	size:	<i>10.00 - 20</i>	
front right	<i>30%</i>	twin / mono:	<i>twin</i>	
front left	<i>30%</i>	spacer rings:	<input checked="" type="checkbox"/>	
rear right	<i>30%</i>	damages or cuts:	<i>no</i>	
rear left	<i>30%</i>	solid:	<input type="checkbox"/>	
<b>problems, details:</b>				
<i>LHS seat console disengagement lever missing</i>				
<i>equipped with pressurized cab</i>				
dimensions for transport L x W x H in mm: <div> <div>© 2022 MEVAS. Liability for hidden defects excluded. Terms/Conditions: <a href="http://www.mevas.net/legal-documents/imprint">www.mevas.net/legal-documents/imprint</a></div> </div>		9,50 m x 2,50 m x 9,50 m		