

CATERPILLAR 140H

Description

Caterpillar 140H, Engine and model Caterpillar 3306, EPA, but sticker not available, Air conditioning, 17.5R25 90%!, Ripper, 6x4, Low profile erops cabin, Hydraulic tip control, Width of the center blade 4.27m, Differential unlock, Beacon, Extensions available, ask for quotation, Hours on the meter 8311, most probably not accurate. , In good and clean condition.



Year	1996
Hours	0
Weight	
Serial number	2ZK01379
Reference	207366

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine and model	Caterpillar 3306
EPA	EPA, but sticker not available
Ripper	✓
Cabin	Low profile erops cabin
Hydraulic tip control	✓
Width of the center blade	4.27m
Beacon	✓
Manual description	Hours on the meter 8311, most probably not accurate.
Overall condition	In good and clean condition.

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Battery box	★★★★★
Radiator grill	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Fuel tank	★★★★★
Pre-cleaner bowl	★★★★★
Sheet metal	★★★★★
Cracks or welds	Yes
Note: Cirkol frame	

ENGINE DETAILS AND CONDITION

Engine number	08Z95206
Arrangement number	1118003
EPA sticker available	No
Air cleaner	Clean
Anti-freeze level °C	-41°C

Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not Working
Gauges	Few don't work
Switches	★★★★★
Warning	No Warnings Available
Mirrors	Not Broken
Cabin glass	Not broken
Windshield wipers	Few don't work
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Steering column	★★★★★

STEERING

Articulate cylinder leaking	No
-----------------------------	----

Play articulate cylinder	★★★★★
Play articulating point	★★★★★
Wheel lean cylinder leaking	No
Play wheel lean cylinder	★★★★★
Steering cylinders leaking	No
Play steering cylinders	★★★★★
Play king pin front axle	★★★★★
Steering frame	★★★★★
Steering pump	★★★★★
Steering operating condition	★★★★★

BLADE

Circle A frame	★★★★★
Play circle A frame	★★★★★
Circle frame	★★★★★
Play circle frame	★★★★★
Cutting edge	★★★★★
Ring gear	★★★★★
Moldboard skin	★★★★★

RIPPER

Play ripper	★★★★★
Lifting cylinder leaking	No
Ripper frame	★★★★★
Number of ripper shanks	3

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play side shift cylinder	★★★★★
Side shift cylinder leaking	No
Play circle shift cylinder	★★★★★
Circle shift cylinder leaking	No
Play tip cylinder	★★★★★
Tip cylinder leaking	No
Hydraulic valves leaking	No

Circle drive oil level ok	Yes
Circle drive leaking	No
Operating condition hydraulics	★★★★☆☆
Noise hydraulic pump normal	Yes

BRAKE

Service brake operation	★★★★☆☆
Parking brake operation	★★★★☆☆
Compressor	★★★★☆☆
Brake pedal	★★★★☆☆

TRANSMISSION

Transmission controls	★★★★☆☆
Transmission noisy	No
Leaks	No
Transmission oil level ok	Yes
Transmission fully operational in all gears forward and reverse	Yes

DRIVE CHAIN/TANDEM

Differential lock/unlock working	Yes
Tandem housing	★★★★☆☆
Left tandem leaking	No
Left tandem oil level ok	Yes
Right tandem leaking	No
Right tandem oil level ok	Yes
Wheel bolts and rims	★★★★☆☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆☆
Batteries	★★★★☆☆
Starter	★★★★☆☆
Head lights working	Yes
Tail lights working	Yes
Signal lights working	No
Additional work lights working	Few lights don't work

SAFETY ITEMS

Backup alarm	Working
--------------	---------

Seat belt	Available
Horn	Not Working
Parking Brake	Working
Beacon	Not Working

TYRES

FRONT LEFT TYRES

Tread dept in mm	26mm
Percentage life remaining	90%

MIDDLE LEFT TYRES

Tread dept in mm	26mm
Percentage life remaining	90%

REAR LEFT TYRES

Tread dept in mm	26mm
Percentage life remaining	90%

REAR RIGHT TYRES

Tread dept in mm	26mm
Percentage life remaining	90%

MIDDLE RIGHT TYRES

Tread dept in mm	26mm
Percentage life remaining	90%

FRONT RIGHT TYRES

Tread dept in mm	26mm
Percentage life remaining	90%

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

