

Evaluation Mobile Material Handler		www.mevas.net		 MEVAS
Customer/Location:	Prima / Hardenberg	vers 12-2024		
Date:	16.12.2025			
Machine / type:	Sennebogen 825	Hour reading:	11.904	
Serial No.:	825.0.684	Year:	2007	
Inspector:	B. Hecker	stick length:	5,70 m	
CE <input checked="" type="checkbox"/> EPA <input type="checkbox"/> A/C <input type="checkbox"/> generator <input type="checkbox"/>		industrial boom <input checked="" type="checkbox"/>	industrial stick <input checked="" type="checkbox"/>	
stabilizer blade <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/> stabilizers <input checked="" type="checkbox"/>	auxiliary lines <input type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>	
cab		cab door	good	
seat, arm rests	good	windows, mirrors	1)	
switches, levers	dust seal on foot pedal broken	wipers, washer	bottom wiper missing	
gauges, warn lights	oil pressure not displayed	floor mat, covers	good	
aircon / heater	N/A / good	cab structure	good	
engine				
leaks & seals	good	Serial No.	21055696	
oil condition & level	oil level too high	cooling system	good	
exhaust, muffler	good	blow by	minor	
smoke	normal	belts & filters	good	
DPF/DEF status	N/A	coolant condition	good	
visual inspection exterior		sheet metal	cooler grills missing	
chassis	good	bumpers	good	
engine hood	gas strut broken	outriggers/blade	LHS aftermarket and bent	
stairs, hand rails	good	lights, batteries	2)	
boom	good	paintwork	peels off on the stick	
stick	good	rims, wheel nuts	good	
hydraulics & drive train		boom cylinders	good	
hoses & lines	several porous and leaking	stick cylinder	cylinders drift	
pump and valve bloc	one valve on rear leaking	bucket cylinder	no	
transmission gear	good	outr/blade cylinders	good	
swivel joint	area oily	universal joints	good	
functional test		swing drive & brake	good	
pins boom	good	pump noises	good	
pins stick	good	slew ring play	2,0 mm	
generator, cab raiser	good	brakes	good	
pins bucket & linkage	no	drive operation	good	
tools		rotation test	N/A	
grapple size, kind	N/A	hoses/connectors	N/A	
arm condition	N/A	pins & bushings	N/A	
tires	mm (%) remaining life	size:	10.00 - 20	
front right	40%	twin / mono:	twin	
front left	25/50%	spacer rings:	<input checked="" type="checkbox"/>	
rear right	0/40%	cuts:	cuts, shunks missing	
rear left	15/40%	solid:	<input checked="" type="checkbox"/>	
problems, details:	<p>1) the windscreen and the left mirrors are cracked</p> <p>2) left front indicator shell missing and cabin lights not working</p>			
<p><i>The machine is general good condition according to the age. Scheduled maintainance recommended.</i></p> <p><i>Several hydraulic components need to be serviced to get it work ready.</i></p>				
dimensions for transport L x W x H in meter:	10,80 m x 3,00 m x 3,40 m			