



CATERPILLAR 735C

Description

Caterpillar 735C, Engine Caterpillar, C15, 333 kW, CE, Air conditioning, 6x6, Erops cabin, 26.5R25, Retarder, Heated body, Big tailgate, Backup camera, Backup alarm, Central lubrication, Beacon, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year	2017
Hours	12250
Weight	31.115 kg
Serial number	CAT0735CJTFJ00263
Reference	209372

Download photos











CONTACT US: SALES@SMITMA.COM +31(0)773999840



INSPECTION REPORT

FEATURES

Engine	Caterpillar
Engine model	C15
Engine power	333 kW
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Heated body	✓
Tailgate	Big tailgate
Backup camera	✓
Backup alarm	✓
Beacon	✓
Hours	Hours certified by Caterpillar
Overall condition	In very good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	****
Decals	****
Bonnet	****
Chassis	****
Steps/ladders	****
Grab irons	****
Cabin	****
Transmission guard	****

ENGINE DETAILS AND CONDITION

Engine number	ENG02030
Arrangement number	3723565

Air cleaner	Clean
Anti-freeze level °C	-32°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	****
Muffler	****
Exhaust stack	****
Engine supports	****
Hoses	****
Good cold start	Yes
Engine power	****
Blow by	****
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	****
Fan	****
Radiator	****

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Total kilometers	70170 km
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	****
Display	****
Warning	No warnings available
Mirrors	Small crack no need to repair
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	****
Interior roof	****

Seat	****
Door lock	Working
FRAME	
Play front suspension frame	****
Play middle suspension frame	****
Play rear suspension frame	****
Play articulation point	****
Shock absorbers articulation point	****
Play body tipping pin	****
Bearings tipping cylinders	****
Shock absorbers body	****
Play rear equalizer	****
Shock absorbers equalizer	****
Cracks or welds	No
BODY	
Condition outside body	****
Body plates	****
Body heating system	****
Note: Uitlaat pijp defect	
Condition tailgate	****
Cracks or welds	No
HYDRAULICS	
Hydraulic oil level ok	Ye
Hydraulic lines and fittings	****
Hydraulic tank/sight glass and cap	****
Hydraulic valves leaking	No
Noise hydraulic pump normal	Ye
Operating condition hydraulics	****
BRAKE	
Brakelines	****
Service brake operation	****
Parking brake operation	****
Compressor	****
Brake pedal	****
DRIVE TRAIN/TRANSMISSION	

Transmission fully operational in all gears	Yes
forward and reverse	
Transmission oil level ok	Yes
Transfer gear box oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level middle axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level middle left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level middle right final drive ok	Yes
Oil level front right final drive ok	Yes
Drive chain leaks	No
ELECTRICAL, STARTING AND CHARGING SYSTEM	Vos
Alternator functioning	Yes
Wiring	****
Batteries	****
Starter	****
	Yes
Cabin lights working	
Tail lights working	Yes
Tail lights working Additional work lights working	Yes
Tail lights working	Yes
Tail lights working Additional work lights working SAFETY ITEMS	Yes Yes Working
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm	Yes Yes
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera	Yes Yes Working Working Available
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera Seat belt	Yes Yes Working Working
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera Seat belt Horn	Yes Yes Working Working Available Working
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera Seat belt Horn Beacon	Yes Yes Working Working Available Working
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera Seat belt Horn Beacon TYRES	Yes Yes Working Working Available Working
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera Seat belt Horn Beacon TYRES FRONT LEFT	Yes Yes Working Working Available Working Working
Tail lights working Additional work lights working SAFETY ITEMS Backup alarm Backup camera Seat belt Horn Beacon TYRES FRONT LEFT Tread dept in mm	Yes Yes Working Working Available Working Working

REAR RIGHT					
Tread dept in	mm				5m
MIDDLE RIGI	нт				
Tread dept in	mm				11 m
FRONT RIGH	Т				
Tread dept in	mm				43n
					QUSTED
New/Excellent ★ ★ ★ ★	Very good	Good	Fair	Poor	SINCE 1960