

VOLVO G930B

Description

Volvo G930B, Engine and model Volvo D8H, 169 kW, EPA, Air conditioning, 14.00-24TG, Scarifier, 6x4, Hydraulic tip control, Width of the center blade 4.27m, Backup camera, Differential unlock, Beacon, New ripper and front blade available, ask for quotation, In very good and very clean condition.



Year	2014
Hours	6098
Weight	15.800 kg
Serial number	VCEG930BA0S576089
Reference	208257

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine and model	Volvo D8H
Engine power in kW	169 kW
EPA	EPA
Hydraulic tip control	✓
Width of the center blade	4.27m
Beacon	✓
Overall condition	In very good and very clean condition.

GENERAL APPEARANCE

Stamped serial number checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Radiator grill	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Draw bar	★★★★★
Transmission guard	★★★★★
Pre-cleaner bowl	★★★★★
Cracks or welds	Yes
Note: Mounting L+R cirkol shift cylinders	

ENGINE DETAILS AND CONDITION

Engine number	11369789
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-32°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★

Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Warning	No Warnings Available
Mirrors	Not Broken
Cabin glass	Small Crack, no need to repair
Display	★★★★★
Windshield wipers	Few don't work
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Steering column	★★★★★

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Note: Little play	
Play articulating point	★★★★★
Wheel lean cylinder leaking	No

Play wheel lean cylinder	★★★★★
Steering cylinders leaking	No
Play steering cylinders	★★★★★
Play king pin front axle	★★★★★
Steering frame	★★★★★
Steering pump	★★★★★
Steering operating condition	★★★★★

BLADE

Circle A frame	★★★★★
Play circle A frame	★★★★★
Circle frame	★★★★★
Play circle frame	★★★★★
Cutting edge	★★★★★
Ring gear	★★★★★
Moldboard skin	★★★★★

SCARIFIER

Play scarifier	★★★★★
Lifting cylinder leaking	No
Scarifier frame	★★★★★
Number of shanks	5

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play side shift cylinder	★★★★★
Side shift cylinder leaking	No
Play circle shift cylinder	★★★★★
Circle shift cylinder leaking	No
Play tip cylinder	★★★★★
Tip cylinder leaking	No
Hydraulic valves leaking	No
Circle drive oil level ok	Yes
Circle drive leaking	No
Operating condition hydraulics	★★★★★

Noise hydraulic pump normal	Yes
BRAKE	
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★
TRANSMISSION	
Transmission controls	★★★★★
Transmission noisy	No
Leaks	No
Transmission oil level ok	Yes
Transmission fully operational in all gears forward and reverse	Yes
DRIVE CHAIN/TANDEMS	
Differential lock/unlock working	Yes
Tandem housing	★★★★★
Left tandem leaking	No
Left tandem oil level ok	Yes
Right tandem leaking	No
Right tandem oil level ok	Yes
Wheel bolts and rims	★★★★★
ELECTRICAL, STARTING AND CHARGING SYSTEM	
Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Head lights working	Yes
Tail lights working	Few lights don't work
Signal lights working	Few lights don't work
SAFETY ITEMS	
Backup alarm	Not Working
Backup camera	Working
Seat belt	Available
Horn	Working
Parking Brake	Working

TYRES

FRONT LEFT TYRES

Tread dept in mm	10mm
------------------	------

Percentage life remaining	40%
---------------------------	-----

MIDDLE LEFT TYRES

Tread dept in mm	14mm
------------------	------

Percentage life remaining	60%
---------------------------	-----

REAR LEFT TYRES

Tread dept in mm	15mm
------------------	------

Percentage life remaining	60%
---------------------------	-----

REAR RIGHT TYRES

Tread dept in mm	13mm
------------------	------

Percentage life remaining	60%
---------------------------	-----

MIDDLE RIGHT TYRES

Tread dept in mm	14mm
------------------	------

Percentage life remaining	60%
---------------------------	-----

FRONT RIGHT TYRES

Tread dept in mm	11mm
------------------	------

Percentage life remaining	50%
---------------------------	-----

New/Excellent



Very good



Good



Fair



Poor

