

## CATERPILLAR CP76

### Description

Caterpillar CP76, Caterpillar , C6.6, EPA, Erops cabin, 23.1-26, Air conditioning, Backup camera, Backup alarm, Hours certified by Caterpillar, In very good and clean condition.



Year	2011
Hours	5394
Weight	16.680 kg
Serial number	CAT0CP76TC7L00155
Reference	206754

[Download photos](#)

### CONTACT US:

[SALES@SMITMA.COM](mailto:SALES@SMITMA.COM)

+31(0)773999840

New/Excellent  
★★★★★

Very good  
★★★★★

Good  
★★★★★

Fair  
★★★★★

Poor  
★★★★★



# INSPECTION REPORT

---

## FEATURES

Engine brand	Caterpillar
Engine model	C6.6
EPA	✓
Tyre size	23.1-26
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

## DOCUMENTS

Parts book	✓
Operation manual	✓

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★★
Cabin	★★★★☆

## ENGINE DETAILS AND CONDITION

Engine number	C6E32191
EPA sticker available	No
Air cleaner	New
Anti-freeze level °C	-15°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★☆
Good cold start	Yes

Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## SAFETY ITEMS

Backup alarm	Not Working
Backup camera	Not Working
Seat belt	Available
Horn	Working
Parking brake	Working

## OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Not Working
Heater	Not Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

## DRUM

Vibratory system	★★★★★
Drum surface	★★★★★

Rubber mounts	★★★★★
Drum scrapers	★★★★★
Leakages	No
Drum oil level ok	Yes
Vibration	High and low vibration frequency working

## STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

## DRIVE CHAIN

Oil level rear axle ok	Yes
Rear axle leakages	No
Wheel bolts and rims	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★

## TYRES

REAR LEFT TYRES	
Tread dept in mm	24mm
Percentage life remaining	50%

## REAR RIGHT TYRES

Tread dept in mm 24mm

Percentage life remaining 60%



Copyright Smitna BV