

INSPECTION REPORT

DYNAPAC CA512D

The Dynapac CA512D is a robust self-propelled roller from 2008, featuring a Cummins QSB6.7 engine with 129 kW power. This machine includes an EROPS cabin, air conditioning, backup alarm, beacon, and fast fuel system. It is equipped with 23.1-26 tires and an AM/FM radio. Weighing 15,650 kg and measuring 6.05 x 2.36 x 3.00 meters, it is in good and clean condition with 5102 running hours.



Specifications

Year	2008
Hours	5102
Weight	15.650 kg
Serial number	70421171
Reference	212572

Features

Engine brand	Cummins
Engine model	QSB6.7
Engine power in kW	129 kW
EPA	✓
Tyre size	23.1-26
Beacon	✓
Overall condition	In good and clean condition.

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★

Engine Details And Condition

Engine number	21868839
EPA sticker available	Yes
Air cleaner	New
Anti-freeze level °C	-15°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

Safety Items

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working
Beacon	Working

Operator Station

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Few don't work
Switches	★★★★★
Display	★★★★★
Warnings	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

Drum

Vibratory system	★★★★★	
Drum surface	★★★★★	
Rubber mounts	★★★★★	
Drum scrapers	★★★★★	
Leakages		No
Drum oil level ok		Yes
Vibration	High and low vibration frequency working	

Steering

Articulate cylinder leaking		No
Play articulate cylinder	★★★★★	
Play articulating point	★★★★★	

Hydraulics

Hydraulic oil level ok		Yes
Hydraulic lines and fittings	★★★★★	
Hydraulic tank/sight glass and cap	★★★★★	
Noise hydraulic pump normal		Yes
Operating condition hydraulics	★★★★★	

Drive Chain

Rear axle leakages		No
Wheel bolts and rims	★★★★★	
Travel motors	★★★★★	
Oil level left final drive ok		Yes
Left final drive leaking		No
Oil level right final drive ok		Yes
Right final drive leaking		No

Electrical, Starting And Charging System

Alternator functioning		Yes
Wiring	★★★★★	
Batteries	★★★★★	
Starter	★★★★★	
Cabin lights working		Yes
Tail lights working		No

Tyres

Rear Left Tyres

Percentage life remaining	50%
---------------------------	-----

Rear Right Tyres

Percentage life remaining

50%



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)



sales@smitma.com



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)