

AMMANN ASC110 D

Description

Ammann ASC 110D, Cummins, QSB4.5, 119kW, EPA, CE, Erops cabin, 23,1-26, Backup alarm, Genuine hours, In very good and clean condition.



Year	2007
Hours	3351
Weight	11.495 kg*
Serial number	107083/1026
Reference	210496

[Download photos](#)

CONTACT US:

SALES@SMITMA.COM

+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★



INSPECTION REPORT

FEATURES

Engine brand	Cummins
Engine model	QSB4.5
Engine power in kW	119kW
EPA	✓
CE	✓
Tyre size	23,1-26
Hours	Genuine hours
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★☆

ENGINE DETAILS AND CONDITION

Engine number	21797392
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-47°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★

Hoses	
Good cold start	Yes
Engine power	
Blow by	
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	
Fan	
Radiator	

SAFETY ITEMS

Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Heater	Working
Gauges	Working
Switches	
Warnings	No warnings available
Mirrors	Small crack, no need to repair
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	
Interior roof	
Seat	

DRUM

Vibratory system	
Drum surface	
Rubber mounts	
Drum scrapers	
Leakages	No

Drum oil level ok	Yes
Vibration	High and low vibration frequency working
Drum measured in mm	23mm

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

DRIVE CHAIN

Oil level rear axle ok	Yes
Rear axle leakages	No
Wheel bolts and rims	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

TYRES

REAR LEFT TYRES	
Tread dept in mm	11mm
Percentage life remaining	50%

Retreaded

No

REAR RIGHT TYRES

Tread dept in mm

14mm

Percentage life remaining

50%

Retreaded

No

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

Copyright Smitma BV

