

Evaluation Mobile Material Handler		www.mevas.net	 <small>© 2022 MEVAS Liability for hidden defects excluded.</small>
Customer/Location:	Prima / Hardenberg	vers 12-2024	
Date:	15.12.2025		
Machine / type:	Terex Fuchs MHL340	Hour reading:	12364
Serial No.:	340210 / 1363	Year:	2007
Inspector:	B. Hecker	stick length:	6,00 m
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/> generator <input type="checkbox"/>		industrial boom <input checked="" type="checkbox"/>	industrial stick <input type="checkbox"/>
stabilizer blade <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/> stabilizers <input checked="" type="checkbox"/>	auxiliary lines <input checked="" type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>
cab		cab door	good
seat, arm rests	good	windows, mirrors	good
switches, levers	1)	wipers, washer	top wiper not working
gauges, warn lights	good	floor mat, covers	cut and worn
aircon / heater	one air vent broken	cab structure	good
engine			
leaks & seals	no leaks seen	Serial No.	10271811
oil condition & level	good	cooling system	limited access
exhaust, muffler	good	blow by	minor
smoke	normal	belts & filters	good
DPF/DEF status	N/A	coolant condition	no access to reservoir
visual inspection exterior		sheet metal	good
chassis	good	bumpers	good
engine hood	good	outriggers/blade	good
stairs, hand rails	good	lights, batteries	batteries broken
boom	good	paintwork	faded
stick	good	rims, wheel nuts	good
hydraulics & drive train		boom cylinders	good
hoses & lines	some porous hoses	stick cylinder	good
pump and valve bloc	good	bucket cylinder	N/A
transmission gear	good	outr/blade cylinders	good
swivel joint	appears to be leaking	universal joints	good
functional test		swing drive & brake	good
pins boom	good	pump noises	good
pins stick	good	slew ring play	1,0 mm without tool
generator, cab raiser	good	brakes	good
pins bucket & linkage	no	drive operation	good
tools		rotation test	N/A
grapple size, kind	N/A	hoses/connectors	N/A
arm condition	N/A	pins & bushings	N/A
tires	mm (%) remaining life	size:	10.00 - 20
front right	60%	twin / mono:	twin
front left	60%	spacer rings:	<input checked="" type="checkbox"/>
rear right	60%	cuts:	?
rear left	60%	solid:	<input checked="" type="checkbox"/>
problems, details:	<p>some error message displayed see video</p> <p>hydraulic pump stalls engine</p> <p>battery cover not attached</p> <p>1) steering wheel losse, rubber knobs on joystick missing</p>		
<p><i>The machine is in general good condition. Some smaller repairs and replacements required.</i></p>			
dimensions for transport L x W x H in meter:	11,00 m x 3,00 m x 3,30 m		