

|  |  |  |  |
|--|--|--|--|
| <b>Evaluation Wheel Loader</b>   |  | <a href="http://www.mevas.net">www.mevas.net</a> |  |
| Customer: <i>Prima</i>   |  | vers 12-24                                       |  |
| Date:  | 17.12.2025   |  |  |
| Machine / type:  | <i>Hyundai HL980</i>   | location:  | <i>Hardenberg</i>  |
| Serial No.:  | <i>HHKHW800EH0000095</i>   | Hour reading:                                    | <i>8252</i>  |
| Inspector:   | <i>B. Hecker</i>   | Year:  | <i>2018</i>  |
| CE <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/>                     | EPA <input type="checkbox"/> Auto-Greaser <input checked="" type="checkbox"/>                        | Hydrostat <input type="checkbox"/>               | quick coupler <input type="checkbox"/>   |
| 3rd valve <input checked="" type="checkbox"/>  | supplemental steering <input type="checkbox"/>   | weigh load <input type="checkbox"/>              | Parts book <input type="checkbox"/> Op-Manual <input type="checkbox"/>             |
| <b>cab</b>   |  | cab door   | <i>good</i>  |
| seat, arm rests  | <i>good</i>  | windows, mirrors                                 | <i>cracked windscreen</i>  |
| switches, levers   | <i>good</i>  | wipers, washer                                   | <i>good</i>  |
| gauges & lamps   | <i>Zu 1.</i>   | floor mat  | <i>good</i>  |
| aircon / heater  | <i>good</i>  | cab structure                                    | <i>good</i>  |
| <b>engine</b>  |  |  |  |
| leaks & seals  | <i>seepage on oil pan</i>  | Serial No.                                       | <i>6cylinder SCANIA no plate found</i>   |
| oil condition & level  | <i>good</i>  | DPF&DEF status                                   | <i>good</i>  |
| exhaust, muffler   | <i>good</i>  | cooling system                                   | <i>good</i>  |
| smoke  | <i>normal</i>  | belts & filters                                  | <i>good</i>  |
| blow by  | <i>minor</i>   | coolant condition                                | <i>low level</i>   |
| <b>exterior</b>  |  | counterweight                                    | <i>good</i>  |
| chassis & lift arm   | <i>good</i>  | fenders  | <i>1)</i>  |
| engine hood  | <i>good</i>  | lights, batteries                                | <i>good</i>  |
| stairs, hand rails   | <i>good</i>  | paintwork  | <i>some scratches</i>  |
| <b>power train</b>   |  | rims, wheel nuts                                 | <i>good</i>  |
| axles/differentials  | <i>good</i>  | universal joints                                 | <i>good</i>  |
| gearbox  | <i>good</i>  | transfer gear                                    | <i>good</i>  |
| power train  | <i>good</i>  | transm. noises                                   | <i>normal</i>  |
| <b>hydraulics</b>  |  | steering cylinders                               | <i>good</i>  |
| hoses & lines  | <i>good</i>  | pumps & valves                                   | <i>good</i>  |
| lift & tilt cylinders  | <i>good</i>  | steering orbital                                 | <i>good</i>  |
| <b>functional test</b>   | full bucket lift in seconds:   |  | <i>7,5 sec.</i>  |
| steering   | <i>good</i>  | articulation play                                | <i>good</i>  |
| transmission test  | <i>good</i>  | loader pins                                      | <i>some play in tilt bushings</i>  |
| stall test   | <i>2100-&gt;2020-&gt;1820rpm</i>   | electric system                                  | <i>warnings displayed</i>  |
| brake / park brake   | <i>good</i>  | suppl. steering                                  | <i>good</i>  |
| <b>bucket</b>  |  | width / capacity                                 | <i>5,6 m<sup>3</sup></i>   |
| edges / teeth  | <i>good</i>  | side condition                                   | <i>good</i>  |
| bottom   | <i>good</i>  | quick coupler                                    | <i>no</i>  |
| <b>tires</b>   | <b>mm (%) good</b>   | <b>size, brand, comments</b>                     |  |
| front right  | <i>40%</i>   | <i>29,5 R25 Triangle</i>                         |  |
| front left   | <i>20%</i>   | <i>29,5 R25 Triangle</i>                         |  |
| rear right   | <i>15%</i>   | <i>29,5 R25 Triangle - porous</i>                |  |
| rear left  | <i>0%</i>  | <i>29,5 R25 Triangle - porous</i>                |  |
| <b>problems, details:</b>  | <i>1) rear right fender bent, front plastic extensions cracked</i><br><i>RHS battery box is dent</i> |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
| <i>The machine is in general good condition but full service and one new tire are recommended.</i> |  |  |  |
| <i>Hydraulic oil change or kidney loop required.</i>   |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
| transport dimensions L x W x H in meter:   | <i>9,40 m x 3,45 m x 3,90 m</i>  |  |  |