

Evaluation Screen Plant on Wheels		www.mevas.net		
Customer/Location:	<i>Prima / Hardenberg</i>	vers 02-22		
Machine/type:	<i>Mustang</i>			
Serial No.:	<i>14118</i>	Hour reading:	<i>11064</i>	
Inspector:	<i>B. Hecker</i>	Year:	<i>2002</i>	
CE <input type="checkbox"/>	Primary Screen <input checked="" type="checkbox"/>	Secondary Screen <input type="checkbox"/>		
Remote Control (cable) <input type="checkbox"/>		Remote Control <input type="checkbox"/>		
engine		Serial No.	<i>plate worn</i>	
leaks	<i>none seen</i>	noises/smoke	<i>good</i>	
oil condition	<i>good</i>	blow by	<i>minor</i>	
exhaust, muffler	<i>good</i>	belts	<i>good</i>	
cooling system	<i>coolant level low</i>	air filter	<i>good</i>	
visual inspection exterior		sheet metal	<i>several covers bent</i>	
engine hood	<i>good</i>	conveyor frames	<i>good</i>	
steps, hand rails	<i>N/A</i>	conveyor belts	<i>porous and patched</i>	
catwalks	<i>N/A</i>	feeder walls	<i>good</i>	
paintwork	<i>some rust</i>	chassis	<i>good</i>	
hydraulics		hydraulic cylinders	<i>one rod bent, one rusty</i>	
hoses & lines	<i>some porous hoses</i>	conveyor motors	<i>good</i>	
controls & valves	<i>good</i>	vibrators	<i>N/A</i>	
work test		screen adjustment	<i>N/A</i>	
conveyors	<i>not tested</i>	screen vibration	<i>N/A</i>	
conveyor folder	<i>N/A</i>	conveyor rollers	<i>not tested</i>	
feeder hopper	<i>N/A</i>	grizzly lift	<i>N/A</i>	
feeder		springs	<i>N/A</i>	
walls & liners	<i>slight dents in walls</i>	wear	<i>40% remaining</i>	
grizzly fingers	<i>N/A</i>	cracks	<i>none seen</i>	
trailer		park brake	<i>good</i>	
tire remaining life	<i>20% remaining</i>	service brake	<i>good</i>	
tire damages	<i>front right cut</i>	outriggers	<i>good</i>	
electric system		emergency switches	<i>not working</i>	
lights	<i>good</i>	wiring, cables	<i>no</i>	
switch board	<i>good</i>	remote control	<i>no</i>	
problems, details:				
<i>The machine is in fair condition. Engine runs well. Some replacements required.</i>				