



CATERPILLAR 745 04A - NEW TIRES

Description

Caterpillar 745 04A, Engine Caterpillar, C18, 376 kW, CE, Air conditioning, 6x6, Erops cabin, 29.5R25 NEW!, GALAXY HTSR 400, Retarder, Big tailgate, Backup camera, Backup alarm, Central lubrication, Beacon, Fast fuel system, Hours certified by Caterpillar, In very good and very clean condition.



Year	2018
Hours	9996
Weight	33.000 kg
Serial number	CAT00745C3T600957
Reference	208679











CONTACT US: SALES@SMITMA.COM +31(0)773999840



INSPECTION REPORT

FEATURES

Engine	Caterpillar
Engine model	C18
Engine power	376 kW
CE	√
Air conditioning	√
Configuration	6x6
Erops cabin	✓
Retarder	✓
Tailgate	Big tailgate
Backup camera	✓
Backup alarm	√
Beacon	√
Overall condition	In very good and very clean condition.

DOCUMENTS

Parts	book	√
Opera	ation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	****
Decals	****
Bonnet	****
Chassis	****
Steps/ladders	****
Grab irons	****
Cabin	****
Transmission guard	****

ENGINE DETAILS AND CONDITION

Engine number	RDP06055
Air cleaner	Clean
Anti-freeze level °C	-50°C
Diesel anti-freeze added	Yes

Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	****
Muffler	****
Exhaust stack	****
Engine supports	****
Hoses	****
Good cold start	Yes
Engine power	****
Blow by	****
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	****
Fan	****
Radiator	****

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Not working
Heater	Working
Gauges	Working
Switches	****
Display	****
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	****
Interior roof	****
Seat	****
Door lock	Working

FRAME

Play front suspension frame	****
Play middle suspension frame	****
Play rear suspension frame	****
Play articulation point	****
Shock absorbers articulation point	****
Play body tipping pin	****
Bearings tipping cylinders	****
Shock absorbers body	****
Play rear equalizer	****
Shock absorbers equalizer	****
Cracks or welds	No
BODY	
Condition outside body	****
Body plates	****
Condition tailgate	****
HYDRAULICS	
Hydraulic oil level ok	Yes
Hydraulic lines and fittings	****
Hydraulic tank/sight glass and cap	****
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	****
BRAKE	
Brakelines	***
Service brake operation	****
Parking brake operation	****
Compressor	****
Brake pedal	****
DRIVE TRAIN/TRANSMISSION	
Transmission fully operational in all gears	Yes
forward and reverse	
Transmission oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes
Oil level middle axle ok	Yes

Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level middle left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level middle right final drive ok	Yes
Oil level front right final drive ok	Yes
Drive chain leaks	No
ELECTRICAL, STARTING AND CHARGING SYSTEM	
Alternator functioning	Yes
Wiring	****
Batteries	****
Starter	****
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes
SAFETY ITEMS	
Backup alarm	Working
Backup camera	Working
Seat belt Seat b	Available
Horn	Working
Beacon	Working
ΓYRES	
FRONT LEFT	
Tread dept in mm	56mm
Percentage life remaining	100%
MIDDLE LEFT	
Tread dept in mm	56mm
Percentage life remaining	100%
REAR LEFT	
Tread dept in mm	56mm
Tread dept in mm Percentage life remaining	56mm 100%

. romaining				
e remaining				100%
Т				
nm				56mm
remaining				100%
-				
nm				56mm
eremaining				100%
				SUSTED
Very good ★ ★ ★ ★ ★	Good ★ ★ ★ ★ ★	Fair ★★★★★	Poor ★ ★ ★ ★ ★	SINCE 1960
				PARTHE
	nm e remaining nm e remaining	nm e remaining nm e remaining very good Good	nm e remaining nm e remaining Very good Good Fair	nm e remaining nm e remaining very good Good Fair Poor