



CATERPILLAR 140M3

Description

Caterpillar 140M3, Engine and model Caterpillar C9.3, EPA, Air conditioning, 17.5R25, Push block, Ripper, 6x4, Auto shift, Hydraulic tip control, Width of the center blade 4.32m, Blade lift accumulators, Backup camera, Differential unlock, Prepared for GPS, AM/FM Radio, Hours certified by Caterpillar, Extensions available, ask for quotation, In very good and very clean condition.



Year	2018
Hours	10339
Weight	19.000 kg
Serial number	CAT0140MEN9D01035
Reference	208029









CONTACT US: SALES@SMITMA.COM

+31(0)773999840

New/Excellent

Very good

Good

Fair ★★★★★ Poor ★ ★ ★ ★



INSPECTION REPORT

FEATURES

Engine and model	Caterpillar C9.3
EPA	EPA
Push block	✓
Ripper	✓
Hydraulic tip control	✓
Width of the center blade	4.32m
Overall condition	In very good and very clean condition.

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	****
Decals	****
Bonnet	****
Engine cover doors	****
Radiator grill	****
Steps/ladders	****
Grab irons Grab irons	****
Cabin	****
Fuel tank	****
Transmission guard	****
Pre-cleaner bowl	****
Sheet metal	****
Cracks or welds	No

ENGINE DETAILS AND CONDITION

SYE23375
516-9592
Yes
Clean
-41°C
Yes
Yes
Yes
Yes

Exhaust manifold	****
Muffler	****
Exhaust stack	****
Engine supports	****
Hoses	****
Good cold start	Yes
Engine power	****
Blow by	****
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	****
Fan	****
Radiator	****

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	****
Warning	No Warnings Available
Mirrors	Not Broken
Cabin glass	Small Crack, no need to repair
Display	****
Windshield wipers	Working
Interior lights	Working
Cabin floor	****
Interior roof	****
Seat	****

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	****
Play articulating point	****
Wheel lean cylinder leaking	No

Play wheel lean cylinder	****
Steering cylinders leaking	No
Play steering cylinders	****
Play king pin front axle	****
Steering frame	****
Steering pump	****
Steering operating condition	****
BLADE	
Circle A frame	****
Play circle A frame	****
Circle frame	****
Play circle frame	****
Cutting edge	****
Ring gear	****
Moldboard skin	****
RIPPER	
Play ripper	****
Lifting cylinder leaking	No
Ripper frame	****
Number of ripper shanks	3
HYDRAULICS	
Hydraulic oil level ok	Yes
Blade lift accumulators	2
Hydraulic lines and fittings	****
Hydraulic tank/sight glass and cap	****
Play lift cylinder	****
Note: Little play Yoke	
Lift cylinders leaking	No
Play side shift cylinder	****
Side shift cylinder leaking	No
Play circle shift cylinder	****
Circle shift cylinder leaking	No
Play tip cylinder	****
Tip cylinder leaking	No
Hydraulic valves leaking	No
Circle drive oil level ok	Yes
Circle drive leaking	No

Operating condition hydraulics	****
Noise hydraulic pump normal	Yes
BRAKE	
Brakelines	****
Service brake operation	****
Parking brake operation	****
Compressor	****
Brake pedal	****
TRANSMISSION	
Transmission controls	****
Transmission noisy	No
Leaks	No
Transmission oil level ok	Yes
Transmission fully operational in all gears	Yes
forward and reverse	
DRIVE CHAIN/TANDEMS	
Differential lock/unlock working	Ye
Tandem housing	****
Left tandem leaking	No
Left tandem oil level ok	Ye
Right tandem leaking	No
Right tandem oil level ok	Yes
Wheel bolts and rims	****
ELECTRICAL, STARTING AND CHARGING SYSTEM	
Alternator functioning	Ye
Wiring	****
Batteries	****
Starter	****
Head lights working	Ye
Tail lights working	Yes
Signal lights working	Yes
Additional work lights working	Yes
SAFETY ITEMS	
Dealuse alarma	Working
Backup alarm	VVOI KIII

Seat belt			Availabl
Horn			Workin
Parking Brake			Workin
TYRES			
FRONT LEFT	TYRES		
Tread dept in	mm		9mm
MIDDLE LEF	T TYRES		
Tread dept in	mm		22mm
REAR LEFT T	YRES		
Tread dept in	mm		23mm
REAR RIGHT	TYRES		
Tread dept in	mm		21mm
MIDDLE RIG	HT TYRES		
Tread dept in	mm		22mm
FRONT RIGH	IT TYRES		
Tread dept in	mm		9mm
			ISTED