



CATERPILLAR 328D LCR

Description

Caterpillar 328D LCR, Engine brand and model Caterpillar C7, 140 kW, CE, Air conditioning, Central lubrication, Backup camera, Beacon, Width of the pads 600mm, Mono boom, Length of the mono boom 6.15m, Length of the stick 3.20m, Digging bucket with teeth, Width of the bucket 1.47m, Piped for hammer, Burst valve on lift cylinder, Hours certified by Caterpillar, In good and clean condition.



Year	2009
Hours	12121
Weight	36.500 kg
Serial number	CAT0328DAMKR00231
Reference	208108











CONTACT US: SALES@SMITMA.COM +31(0)773999840













INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar C7
Engine power in kW	140 kW
CE	√
Air conditioning	✓
Width of the pads	600mm
Boom	Mono boom
Length of the mono boom	6.15m
Length of the stick	3.20m
Bucket	Digging bucket with teeth
Width of the bucket	1.47m
Piped	Piped for hammer
Overall condition	In good and clean condition.
DOCUMENTS	
Parts book	✓
Operation manual	✓
GENERAL APPEARANCE	
Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	****
Body work	****
Decals	
——————————————————————————————————————	****
Bonnet	**** ****
Bonnet	****
Bonnet Engine cover doors	**** ****
Bonnet Engine cover doors Chassis	**** **** ***
Bonnet Engine cover doors Chassis Bottom plates	***** ***** ****
Bonnet Engine cover doors Chassis Bottom plates Counter weight	***** ***** ***** ****
Bonnet Engine cover doors Chassis Bottom plates Counter weight Steps/ladders	***** **** **** **** ****

ENGINE DETAILS AND CONDITION

Air cleaner	New
Anti-freeze level °C	-14°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	****
Muffler	****
Exhaust stack	****
Engine supports	****
Hoses	****
Good cold start	Yes
Engine power	****
Blow by	****
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	****
Fan	****
Radiator	****
BUCKET	
Overall condition of the bucket	****
Bottom	****
Sides	****
Teeth	****
UNDERCARRIAGE LEFT IN LIFE IN %	
Overall condition	60%
Chains	60%
Bushings	50%
Sprockets	50%
Idlers	80%
Bottom rollers	30%
Top rollers	70%
Track pads	60%
· · · · · · · · · · · · · · · · · · ·	

SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working
Beacon	Not Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	****
Display	****
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	****
Interior roof	****
Seat	****

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	****
Hydraulic tank/sight glass and cap	****
Travel motors	****
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	****

BOOM AND STICK

Play lift cylinder	****
Lift cylinders leaking	No

Play boom pen	****
Play stick cylinder	****
Stick cylinder leaking	No
Play stick pen	****
Play bucket cylinder	****
Bucket cylinder leaking	No
Play bucket link	****
Play bucket pen	****
Condition monoboom	****
Condition stick	****
SWING CIRCLE	
Play on the swing bearing	****
Swing gear	****
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noice normal	Yes
Hydraulic swivel leaking	No
Operating condition	****
ELECTRICAL, STARTING AND CHARGING SYSTEM	
Alternator functioning	Yes
Wiring	****
Batteries	****
Starter	****
Cabin lights working	Yes
New/Excellent Very good Good Fair Poor 本本本本 本本本本 本本本本 本本本本 本本本本 本本本本 A 本本本本 A 本本本本 A	AUSTED SINCE 1960