Komatsu, 931XC - Harvester Komatsu - Inspection report

Images

















Information

Brand: Komatsu Model: 931XC

Estimated hours at delivery: 10600

Country: Finland Model year: 2021 Year of manufacture: 2021

Serial number: KMTXH021NMZ002367

Delivery date: 16.09.2025 Location: Pirkkala

Base machine

Front axle: Boogie Automatic sprinkler: No

Extinguishing: Only extinguishers

Gear box: Good Paintwork: Clear laquer Tilt plate: Good condition

Rear axle: Boogie Ladder: Good Central lubrication: Yes Hood protection: OK Hydrostatic: **OK**

Tyres

Left-front-front: 70% Left-front-back: 70% Left-back-front: 70% Left-back-back: 70% Brand front: Nokian

Front dimensions: 710/45x26,5

Right-front-front: 70% Right-front-back: 70% Right-back-front: 70% Right-back-back: 70% Brand back: Nokian

Back dimensions: 710/45x26,5

Diesel engine

Engine: Ok

Heatingloop in hydraulic tank: Yes

Electric pump: Yes Diesel heater: Good Cooling system: Fair Electric system: Good Adblue: Working

Hydraulics

Hydraulic system: Good

Valve bank: Good

Other options: Vacuum pump & hydraulic filling pump

Pump: Good Hydraulic oil: Mineral

Cabin

Seat type: 3000 BeGe Crane lever: Good Control system: MaxiXT

GIS system: Gps receiver is there

Windshield: Fair 3 kpl naarmuja, jotka lähtevät hiomalla

Air condition: Good Platform: \mathbf{OK} Service ladder: **OK** Rearview cam: Good Machine folder: Yes

Seat condition: Good Crane lever: EmE advanced Operation monitoring: Yes Work lights: LED Wipers: Front

Sun curtains: Good Radio: Smart radio Data caliper: 500 mm User manual: Yes Parts book: Yes







Crane

Crane: **Good** Length (m): **9,7**

Slew house: **Good** Rotator: **Good** Crane damper: **Yes** Model: 230H

Boom system: Good

Ei havaittuja välyksiä jatkeessa, taitossa, nostossa tai hytin alla. Link: MPB2 Good

Link: MPB2 Good Crane lights: Yes Slewing unit: Good

Harvester head

Make: Komatsu Year: 2021 Condition: Good Multi tree handling: No Feed rollers: Teräs VTec Colour marking: Yes Aut. chain tensioner: Yes

Model: C144 Hours: 10600 Leak tightness: OK Knives: Good Condition: Good Stump treatment: Yes









Extra equipment

Tyre Chain back make: **Pewag**Condition: **40%**Type: **TXL 900mm**



Type: ForstGrip Pro 15,5mm Tracks front make: Clark Condition: 40%

Overall evaluation condition

Overall evaluation condition: Average