

Evaluation Tracked Excavator		www.mevas.net						
Customer/location:	Prima / Hardenberg	vers 12-24						
Date:	19.12.2025							
Machine / type:	Liebherr R924B	Hour reading:	14978					
Serial No.:	WLHZ0761TZC015556	Year:	2005					
Inspector:	B. Hecker	stick length:	shear					
CE label <input checked="" type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	adjustable boom <input type="checkbox"/>	DPF <input type="checkbox"/> DEF (AdBlue) <input checked="" type="checkbox"/>					
auto lube <input checked="" type="checkbox"/>	stick check valve <input checked="" type="checkbox"/>	stabilizer blade <input type="checkbox"/>	A/C <input checked="" type="checkbox"/>					
lines hammer <input checked="" type="checkbox"/>	lines grapple/shear <input checked="" type="checkbox"/>	quick coupler type:	no					
cab		cab door, covers	good					
seat, arm rests	aftermarket - cushion damaged	windows & mirrors	1)					
switches, joysticks	good	wipers, washer	not working					
gauges & warn lights	good	floor mat	good					
aircon / heater	good	cab structure	good					
engine								
leaks & seals	no leaks seen	Serial No.	no plate found					
oil condition & level	good	cooling system	coolant level too low					
exhaust, muffler	good	blow by	minor					
smoke	normal	belts & filters	good					
DPF/DEF status	N/A	coolant condition	too low					
visual inspection exterior		covers / sheets	some bottom covers missing					
chassis, track frame	good	side doors	good					
engine hood	gas strut broken	compartments	good					
steps, hand rails	bent on RHS	bumpers / catwalk	several dents					
boom	good	lights, batteries	lights and battery broken					
stick	N/A	paintwork	good					
hydraulics		boom cylinders	good					
hoses,lines,swivel	good	stick cylinder	good					
pump and valve bloc	good	bucket cylinder	no					
functional test		boom self drift	good					
pins boom	some play	pump noises	good					
pins stick	good	slew ring play	1,2mm play					
pins bucket	N/A	electric system	good					
swing drive/brake	good	drive train	good					
tools		bucket 2, size,type	N/A					
bucket 1, size & type	N/A	condition	N/A					
condition	N/A	coupler condition	N/A					
U/C	remaining life mm (%)	rollers	50%					
bushings	20 %	track links	30 %					
shoes	30 %	sprockets	20 %					
idlers	50 %	track pitch in mm:	773 mm					
carrier rollers	0 % one missing	shoe width in mm:	900 mm					
problems, details								
roof window seal leaking, mirrors cracked or missing								
HKS XS3000 shear from 2008 - welded top mount								
<p><i>The machine is in general good condition. Some smaller repairs and replacements required.</i></p> <p><i>Some parts of the undercarriage need to be replaced.</i></p>								
dimensions for transport L x W x H in meter:		9,60 m x 3,30 m x 3,60 m	© 2022 MEVAS. Liability for hidden defects excluded.					
Terms/Conditions: www.mevas.net/legal-documents/imprint								