

Servicekort

Maskinnr.: A5100972 AXION 830
Serviceværksted: 4291 Danish Agro Machinery Brønderslev - Danmark

Udstyr:

| | | |
|--------|------|--|
| TJ_B02 | 0126 | CLAAS front linkage 4.6 t |
| TJ_351 | 0001 | Relevage Av et/ou Cr Ram |
| TJ_B03 | 0022 | External operation for front linkage and front spool val |
| TJ_B04 | 0000 | Without linkage-mounted weight block |
| TJ_350 | 0000 | sans axe (1 sur rel) |
| TJ_B06 | 0002 | Without front PTO |
| TJ_B08 | 0103 | Without electronic position control |
| TJ_715 | 0001 | Ss Ctrl Pos-Obturateur N4 |
| TJ_I02 | 0041 | CEBIS terminal with touchscreen |
| TJ_709 | 0020 | Accoudoir N4 - avec RAV |
| TJ_713 | 0003 | Obturateur N4 |
| TJ_810 | 0003 | Obturateur N4 PT Suspendu |
| TJ_I04 | 0042 | CMATIC with 2 engine speed memories + CSM, CEBIS |
| TJ_I08 | 0250 | Alternator 250 amp/hour |
| TJ_I10 | 0011 | ISOBUS-ready with ISO rear socket |
| TJ_I18 | 0000 | Without job management |
| TJ_I20 | 0000 | Without CEMOS |
| TJ_I22 | 0050 | AUTO PILOT |
| TJ_I24 | 0000 | Without SAT 900 GNSS receiver |
| TJ_I25 | 0160 | CLAAS communication module (LTE) |
| TJ_I26 | 0070 | TELEMATICS advanced licence – 1 year |
| TJ_I28 | 0000 | Without terminal |
| TJ_I29 | 0190 | CLAAS Remote Service for 5 years |
| TJ_I29 | 0210 | ISOBUS activation for CEBIS |
| TJ_I30 | 0100 | GPS PILOT-ready |
| TJ_I40 | 0000 | Standard steering interface |
| TJ_I32 | 0201 | ELECTROPILOT |
| TJ_I38 | 0030 | Activation of video function in CEBIS |
| TJ_557 | 0030 | Electropilot N4 |
| TJ_J02 | 0050 | ELC with radar sensor & wheel slip control |
| TJ_J04 | 0312 | Lower links, rear linkage, cat. 3 hook |
| TJ_J06 | 0400 | Lower link stabilisers, automatic |
| TJ_443 | 0001 | Supp. Stab GPA41/42/44 |
| TJ_J08 | 0265 | Mechanical top link, cat. 3 hook |
| TJ_J10 | 0311 | Ladder hitch with slot for drawbar |
| TJ_J14 | 0020 | Drawbar, cat. 3 |
| TJ_J16 | 0000 | Without clevis |
| TJ_J18 | 0030 | Ball set, cat. 3/2 |
| TJ_J42 | 0020 | Air brakes (2 lines), with air drier |
| TJ_430 | 0001 | fr Hyd ou PN ss PAV frein |
| TJ_J44 | 0030 | Hydraulic brakes for air brakes |
| TJ_J46 | 0000 | Without ABS connection for trailer |
| TJ_J48 | 0020 | Double pedal with steering brake |
| TJ_K02 | 0205 | LS hydraulic system, variable displacement pump 205 l/mi |
| TJ_K04 | 2040 | 4 spool valves, electrohydraulic proportional |
| TJ_537 | 0030 | Rel.Av&D.EH.Ar ssDEH |
| TJ_K10 | 0030 | Front linkage & 1x da/front connected at the rear |

Servicekort

Maskinnr.: A5100972 AXION 830
Serviceværksted: 4291 Danish Agro Machinery Brønderslev - Danmark

| | | |
|--------|------|--|
| TJ_541 | 0040 | Distrib. EH ss DEH Avt |
| TJ_K12 | 0020 | Power Beyond, load-sensing connections without flat face |
| TJ_N02 | 0040 | CMATIC continuously variable transmission |
| TJ_N04 | 0240 | Transmission ratio 40 km/h |
| TJ_N06 | 0222 | PROACTIV front axle |
| TJ_N26 | 0000 | Without spacer rings, rear axle |
| TJ_N28 | 0000 | Without tyre pressure adjustment system |
| TJ_901 | 0020 | FAM & Contacteur |
| TJ_N08 | 0012 | Rear axle, standard |
| TJ_N10 | 0140 | PTO 540 ECO + 1000/1000 ECO rpm |
| TJ_N14 | 0010 | PTO stub, 6 splines and 21 splines, 1 3/8" |
| TJ_N20 | 0010 | Parking brake on REVERSHIFT lever |
| TJ_N22 | 0361 | Front mudguards, pivoting, 620 mm |
| TJ_N34 | 0000 | Without rear wheel weights |
| TJ_N36 | 0000 | Standard flange |
| TJ_N38 | 0001 | Standard transmission management. |
| TJ_P02 | 0512 | 235 hp max. output, 243 hp type-approved rated output, E |
| TJ_P04 | 0020 | Diesel pre-filter |
| TJ_P06 | 0030 | Battery master switch, electronic |
| TJ_P08 | 0010 | Red diesel |
| TJ_P10 | 0001 | Without cold-start kit |
| TJ_P12 | 0000 | Without diesel pre-filter, heated |
| TJ_P14 | 0010 | Exhaust pipe, standard |
| TJ_P16 | 0401 | Air compressor |
| TJ_P22 | 0010 | Engine brake |
| TJ_Q02 | 0010 | Cab with 4-point suspension |
| TJ_Q04 | 0011 | Roof, without roof hatch |
| TJ_Q06 | 0010 | Rear window |
| TJ_Q08 | 0010 | Rear window wiper |
| TJ_Q14 | 0062 | Electric mirror, with wide-angle mirror |
| TJ_Q18 | 0070 | Lateral mudguard extensions, rear mudguard |
| TJ_Q20 | 0022 | Terminal bar, right-hand side window |
| TJ_Q21 | 0070 | Tool box |
| TJ_Q22 | 0010 | Removable storage box, left |
| TJ_Q30 | 0020 | Additional interface sockets |
| TJ_Q40 | 0030 | 2 high-level headlights, A-pillar |
| TJ_Q50 | 0060 | Extra-wide rear lights, LED with warning signs |
| TJ_Q56 | 0010 | 4x halogen road lights, 2x halogen work lights, bonnet |
| TJ_569 | 0001 | Circul. Droite Halo |
| TJ_Q58 | 0020 | Halogen work lights: 4x roof, front and 4x roof, rear |
| TJ_Q60 | 0020 | Work lights, LED: 2x front, 2x rear, 2x steps (hal.) |
| TJ_R00 | 0000 | Colour, CLAAS Green |
| TJ_R02 | 0300 | CEBIS |
| TJ_R04 | 0120 | Comfort seat, fabric, air-suspension, swivelling |
| TJ_921 | 0001 | couvercle tissu |
| TJ_923 | 0002 | Fixation GRAMMER |
| TJ_R06 | 0020 | Passenger seat with safety belt |
| TJ_R08 | 0030 | Automatic climate control, Cat. 3 ready |
| TJ_R10 | 0030 | MP3 radio with Bluetooth, external mic. for hands-free s |
| TJ_R14 | 0010 | Cigarette lighter |
| TJ_R16 | 0020 | Steering wheel, leather |

Servicekort

Maskinnr.: A5100972 AXION 830
Serviceværksted: 4291 Danish Agro Machinery Brønderslev - Danmark

| | | |
|----------|------|--|
| TJ_R20 | 0000 | Without dynamic steering |
| TJ_S02 | 0001 | Safety sticker, standard |
| TJ_S04 | 0010 | Right-hand drive |
| TJ_S06 | 0040 | 2x rotating beacons, LED |
| TJ_S08 | 0001 | Equipment - European Union |
| TJ_S10 | 0010 | Front number plate holder |
| TJ_S12 | 0000 | Without wheel chocks |
| TJ_S14 | 0000 | Without first aid kit |
| TJ_S16 | 0000 | Without pre-installed fittings for fire-extinguisher |
| TJ_S20 | 0000 | Without tablet holder |
| TJ_S22 | 0010 | Identification plate, EU |
| TJ_T02 | 0010 | Truck transport |
| TJ_102 | 80A2 | 600/65 R28 Mitas AC 65 / adjustable rim |
| TJ_103 | 76F2 | 650/65 R42 Mitas AC 65 / fixed rim |
| TJ_102_A | 80A2 | 650/65 R42 Mitas AC 65 / fixed rim |
| TJ_103_A | 76F2 | 650/65 R42 Mitas AC 65 / fixed rim |
| TJ_105 | 9405 | 21449570/4244 |
| TJ_910 | 0001 | UBM1.1 type 1 |
| TJ_505 | 0001 | Tuyau DIR+FR Ret HYD (EU) |
| TJ_587 | 0004 | Switch N4 |
| TJ_597 | 0001 | Grille standard EU |
| TJ_820 | 0003 | Pt NFR av Pédales |
| TJ_522 | 0000 | Sans Faisceau 522/0010 |
| TJ_635 | 0020 | CCM+sans toit ouvr.opaque |
| TJ_653 | 0010 | Avec CEG voir texte techn |
| TJ_323 | 0010 | ss cam + feux Ail AR LED |
| TJ_327 | 0005 | ss caméra + N4 |
| TJ_327 | 0010 | ss caméra + N2/N4 |
| TJ_609 | 0020 | Rel.Av & CEBIS |
| TJ_931 | 0010 | Pnt Av susp/susp Frein EU |
| TJ_933 | 0010 | Pnt Av fixe/suspendu EU |
| TJ_937 | 0010 | RAV + EU |
| TJ_939 | 0010 | RAV + EU |
| TJ_945 | 0010 | Rel AR et radar + EU |
| TJ_619 | 0010 | RAV+Ss Ctrl de position |
| TJ_651 | 0010 | AUTO PILOT+Pt Avt Std |

Servicekort

Maskinnr.: A5100972 AXION 830
Serviceværksted: 4291 Danish Agro Machinery Brønderslev - Danmark

Aggregater:

| <u>Materiale</u> | <u>Betegnelse</u> | <u>Aggregatnummer</u> |
|--------------------|--|---|
| FA-CODE36 | LOGIN PIN TELEMATICS | EB4DFD |
| FA-NOCODE122 | ISO-UT CEBIS TOUCH | Not required |
| FA-NOCODE123 | CEBIS TOUCH CODE (I38_0030) | Not required |
| 26068591 | GEARBOX | 00000000005918587 |
| 26387582 | SUSPENDED FRONT AXLE | 48539801000318 |
| 11178500 | TRANSMISSION GTA4244 | 11318081 |
| 11017830 | PONT ARR. GPA44 | M071514 |
| 26221363 | ENGINE | 001838594 |
| 27750300 | STEERING GEARBOX HYD | 091F6318 |
| 12632070 | CABINE ASS K07 10T HAYON STD 4 POTEAUX | 50007043-0110210263 |
| 26095301 | CONTROL DESK | A006_--- |
| 27171541 | MONITOR | A030_C090078 |
| 00000340 | MD TYP 034 SUPER AUTOMATIC-S | A056_34.30.0 |
| 11265830 | AUTO5 DC | A058_1462883 |
| 00159331 | SOFTWARE | A062_3.3.9 |
| 26228911 | ARMREST | A100_C080032 |
| 11176710 | PACK SW MFA A09 6PS | A100_2.0.0 |
| 26070263 | INDICATOR | A101_C090080 |
| 11265830 | AUTO5 DC | A102_1462882 |
| 22437120 | WORKING LIGHT PANEL | A104_--- |
| 11265830 | AUTO5 DC | A136_1462881 |
| 11265830 | AUTO5 DC | A142_1462879 |
| 11265830 | AUTO5 DC | A143_1462880 |
| 27680570 | MODULE UCM | A159_C0700178 |
| 27680529 | SOFTWARE UCM | A159_20.14.4 |
| FA-MODUL-A159-0007 | IMEI MODUL (UCM) | A159_352255064304839 |
| FA-MODUL-A159-0008 | ICCID SIM-CARD (UCM) | A159_89490200001672204917 |
| FA-MODUL-A159-0009 | IMSI SIM-CARD (UCM) | A159_262017648525405 |
| FA-MODUL-A159-0010 | UUID (UCM) | A159_705de3e6-a407-5298-b034-fcc2b4cee1bc |
| 27505840 | ELECTRONICAL HOUSING | A210_0.67.32 |
| 27505840 | ELECTRONICAL HOUSING | A210_0.67.32 |
| 00155326 | MODULE | A009_C065729 |