

2247 21724-1

SW 77001550  
ARR 358-9227

800D

455 HRS	500 HR SERVICE	11-17-2014
190 HRS	11-25 TO 12-3 DOWN FOR FAN MOTOR PUMP	
	POMCO REPAIRED	
511 HRS	LOSING HYD OIL OUT FLUSHING HOUSING	
	RETURNED PRILL	12-12-14
1234	250 HR SERVICE	6-8-17
1587	250 HR SERVICE	8-16-17
1981	500 HR	10/14/17
2242	250 HR	12/12/17
2515	250 HR	1/22/18
2928	1000 HR	4/19/18
3141	1000 HR <sup>BY</sup> MISTAKE	6/19/18
3451	1000 HR	
3775	250 HR	9/24/18
4014	1000 HR	11/13/18
4625	250 HR	1/16/19
5014	1000 HR	3/24/19 VG
5314	250 HR	5/29/19 VG
5590	250 HR	7/11/19
5881	1000 HR	10/4/19

800D

21737

10-4-19	1000 HR	5,881	
11-4-19	250 HR	6,128	
4-2-20	250 HR	6,430	
5-28-20	1000 HR	6,625	
8-7-20	250 HR	6,880	
11-9-20	1000 HR	7,150	
<del>11-9-20</del>			
1-21-21	250 HR	7,381	
4-23-21	250 HR	7,665	
6-24-21	250 HR	7,875	
9-2-2021	1,000 HR	8,265	
10-11-2021	250 HR	8,513	
12-22-21	250 HR	9,004	
4-22-21	1,000 HR	9,315	*R+K Leaked,*
6-6-2022	250 HR	9,555	Engine / Fuel pump.
2-1-2023	9800	9,684	L-Oil. W/P / EGR cooler.
9-13-23	500 HR	10,577	
10-10-23	1,000 HR	10,741	oil sample. Am/D.

sent to SAW!