

BOMAG BW24R

Description

Bomag BW 24 R, Cummins , B4.6, 74 kW, EPA, 11.00-20, Erops cabin, Water sprinkler system, Air conditioning, Backup alarm, Beacon, In good and fairly clean condition.



| | |
|---------------|--------------|
| Year | 2008 |
| Hours | 6839 |
| Weight | 14950 kg |
| Serial number | 201530601726 |
| Reference | 206387 |

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

| | |
|--------------------|---------|
| Engine brand | Cummins |
| Engine model | B4.6 |
| Engine power in kW | 74 kW |
| EPA | ✓ |

DOCUMENTS

| | |
|------------------|---|
| Parts book | ✓ |
| Operation manual | ✓ |

GENERAL APPEARANCE

| | |
|-------------------------------|-----------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★ ★ ★ ★ ★ |
| Decals | ★ ★ ★ ★ ★ |
| Bonnet | ★ ★ ★ ★ ★ |
| Cabin | ★ ★ ★ ★ ★ |

ENGINE DETAILS AND CONDITION

| | |
|-----------------------------|-----------|
| Engine number | 21695308 |
| EPA sticker available | Yes |
| Air cleaner | Clean |
| Anti-freeze level °C | -17°C |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★ ★ ★ ★ ★ |
| Muffler | ★ ★ ★ ★ ★ |
| Exhaust stack | ★ ★ ★ ★ ★ |
| Hoses | ★ ★ ★ ★ ★ |
| Good cold start | Yes |
| Engine power | ★ ★ ★ ★ ★ |
| Blow by | ★ ★ ★ ★ ★ |
| Knocking | No |
| Compression in the radiator | No |

| | |
|-------------------|--------|
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | ★★★★★ |
| Fan | ★★★★★ |
| Radiator | ★★★★★ |

SAFETY ITEMS

| | |
|---------------|-----------|
| Backup alarm | Working |
| Seat belt | Available |
| Horn | Working |
| Parking brake | Working |
| Beacon | Working |

OPERATOR STATION

| | |
|-------------------|-----------------------|
| Hourmeter | Working |
| Air conditioning | Working |
| Heater | Working |
| Gauges | Working |
| Switches | ★★★★★ |
| Warnings | No Warnings Available |
| Mirrors | Not broken |
| Cabin glass | Not broken |
| Windshield wipers | Not working |
| Interior lights | Not working |
| Cabin floor | ★★★★★ |
| Interior roof | ★★★★★ |
| Seat | ★★★★★ |

TYRE REGULATION

| | |
|-----------------|-------------|
| Tyre regulation | Not Working |
|-----------------|-------------|

STEERING

| | |
|----------------------------|-------|
| Steering cylinders leaking | No |
| Play steering cylinders | ★★★★★ |

HYDRAULICS

| | |
|------------------------------|-------|
| Hydraulic level ok | Yes |
| Hydraulic lines and fittings | ★★★★★ |

| | |
|------------------------------------|--------|
| Hydraulic tank/sight glass and cap | ★★★★★★ |
| Noise hydraulic pump normal | Yes |
| Operation condition hydraulics | ★★★★★★ |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|--------------------------------|-----------------------|
| Alternator functioning | Yes |
| Wiring | ★★★★★★ |
| Batteries | ★★★★★★ |
| Starter | ★★★★★★ |
| Cabin lights working | Yes |
| Tail lights | Yes |
| Additional work lights working | Few lights don't work |

| | | | | |
|-------------------------|---------------------|----------------|----------------|----------------|
| New/Excellent ★★★★★★ | Very good ★★★★★★ | Good ★★★★★★ | Fair ★★★★★★ | Poor ★★★★★★ |
|-------------------------|---------------------|----------------|----------------|----------------|

Copyright Smitma BV

