

## INSPECTION REPORT

### VOLVO L30G

The Volvo L30G is a high-performance wheel loader designed for efficient operations. Equipped with a Volvo D3.3H engine delivering 55.4kW, this machine includes an EROPS cabin for operator safety and comfort. It features a hydraulic quick release system, a GP bucket with a bolt-on edge measuring 1.90m in width, and forks for versatile handling. With a complete steering wheel, immobilizer, and beacon, the L30G ensures secure functionality. This unit, manufactured in 2014, has genuine hours and is in very good and clean condition.



### Specifications

Year	2014
Hours	6279
Weight	6.650 kg
Serial number	VCCEL30G0003120412
Reference	212464

### Features

Engine and model	Volvo D3.3H
Engine power	55.4kW
CE	✓
Erops cabin	✓
Tyre size	405/70R20
Bucket	GP bucket with bolt on edge
Width of the bucket	1,90m
Steering	Complete steering wheel
Beacon	✓
Hours	Genuine hours
Overall condition	In very good and clean condition.

### Documents

CE document	CE document available
Parts book	✓
Operation manual	✓

## General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Code immobilizer	0000
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

## Engine Details And Condition

Engine number	8EA4041
Air cleaner	Clean
Anti-freeze level °C	-35°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## Operator Station

Hourmeter	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

## Bucket

Overall condition of the bucket	★ ★ ★ ★ ★
Bottom	★ ★ ★ ★ ★
Sides	★ ★ ★ ★ ★
Cutting edge	★ ★ ★ ★ ★

## Frame

Play articulation point	★ ★ ★ ★ ★
Play loading frame	★ ★ ★ ★ ★
Play bucket pins	★ ★ ★ ★ ★
Crack or welds	No

## Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★ ★ ★ ★ ★
Hydraulic tank/sight glass and cap	★ ★ ★ ★ ★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★ ★ ★ ★ ★

## Brake

Service brake operation	★ ★ ★ ★ ★
Parking brake operation	★ ★ ★ ★ ★

## Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Drivetrain leaks	No

## Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★ ★ ★ ★ ★
Batteries	★ ★ ★ ★ ★
Starter	★ ★ ★ ★ ★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

## Safety Items

Seat belt	Available
Horn	Working
Beacon	Working

## Tyres

### Front Left

Tread dept in mm	14mm
Percentage life remaining	50%
Retreaded	No

### Rear Left

Tread dept in mm	13mm
Percentage life remaining	50%
Retreaded	No

### Rear Right

Tread dept in mm	13mm
Percentage life remaining	50%
Retreaded	No

### Front Right

Tread dept in mm	13mm
Percentage life remaining	50%
Retreaded	No



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)



[sales@smitma.com](mailto:sales@smitma.com)



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)