SMITMA
HEAVY EQUIPMENT

INSPECTION REPORT

VOGELE MT3000-2 OFFSET

The Vogele MT3000-2 OFFSET is a high-performance asphalt paver featuring a robust Deutz engine (TCD 2012 L06 2V) delivering 142 kW. This track-driven machine comes with a hard cover roof and is certified with EPA and CE marks, ensuring compliance with global environmental and safety standards. Built in 2011 and weighing 23,800 kg, this paver is in excellent condition, displaying genuine hours of usage (3054 hours). Its dimensions are 14.95 x 3.02 x 3.85 meters, providing a stable and adaptable platform for pavement operations.



Specifications

Year	2011
Hours	3054
Weight	23.800 kg
Serial number	07610012
Reference	214615

Features

Engine brand	Deutz
Engine model	TCD 2012 L06 2V
Engine power in kW	142kW
EPA	✓
CE	✓
Track driven	✓
Roof	Hard cover roof
Hours	Genuine hours
Overall condition	In very good and very clean condition

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★☆
Decals	★★★☆☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Cracks or welds	No

Engine Details And Condition

Engine number	11002476
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-25°C
Diesel anti-freeze	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★☆
Engine supports	★★★★☆
Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆
Blow by	★★★★☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

Undercarriage Left In Life In %

Overall condition	80%
Track pads	80%
Track chains and sprockets	80%

Operator Station

Hourmeter	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Seat	★★★★☆

Hydraulics

Hydraulic oil level	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

Drive Train/ Transmission

Transmission noisy	No
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Drivetrain leaks	No

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	Yes
Additional work lights working	Yes

Safety Items

Backup alarm	Working
Horn	Working

+31 (0) 77 3999 840 sales@smitma.com +31 (0) 77 3999 840