

## VOLVO G930 - CE

### Description

Volvo G930, Engine and model Volvo D7E GCE3, 150 kW, EPA, CE, 17.5-25, Ripper, 6x4, Hydraulic tip control, Width of the center blade 4.27m, Differential unlock, Beacon, Extensions available, ask for quotation, In good and very clean condition.



Year	2010
Hours	8465
Weight	17.650 kg
Serial number	VCE0G930A00041117
Reference	206600



[Download photos](#)

**CONTACT US:**  
**SALES@SMITMA.COM**  
**+31(0)773999840**

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



# INSPECTION REPORT

## FEATURES

Engine and model	Volvo D7E GCE3
Engine power in kW	150 kW
EPA	EPA
CE	✓
Ripper	✓
Hydraulic tip control	✓
Width of the center blade	4.27m
Beacon	✓
Overall condition	In good and very clean condition.

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Radiator grill	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Transmission guard	★★★★☆
Pre-cleaner bowl	★★★★☆
Sheet metal	★★★★☆
Cracks or welds	No

## ENGINE DETAILS AND CONDITION

Engine number	10509495
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-38°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★☆☆

Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Heater	Working
Gauges	Working
Switches	★★★★★
Mirrors	Not Broken
Cabin glass	Not broken
Display	★★★★★
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Steering column	★★★★★

Note: No steering column adjustment

## STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★
Wheel lean cylinder leaking	No
Play wheel lean cylinder	★★★★★

Steering cylinders leaking	No
Play steering cylinders	★★★★★
Play king pin front axle	★★★★★
Note: Little play	
Steering frame	★★★★★
Steering pump	★★★★★
Steering operating condition	★★★★★

## BLADE

Circle A frame	★★★★★
Play circle A frame	★★★★★
Circle frame	★★★★★
Play circle frame	★★★★★
Note: Little play	
Cutting edge	★★★★★
Ring gear	★★★★★
Moldboard skin	★★★★★

## RIPPER

Play ripper	★★★★★
Lifting cylinder leaking	No
Ripper frame	★★★★★
Number of ripper shanks	3

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Play lift cylinder	★★★★★
Note: Little play	
Lift cylinders leaking	No
Play side shift cylinder	★★★★★
Side shift cylinder leaking	No
Play circle shift cylinder	★★★★★
Circle shift cylinder leaking	No
Play tip cylinder	★★★★★
Tip cylinder leaking	No
Hydraulic valves leaking	No
Circle drive leaking	No
Operating condition hydraulics	★★★★★

Noise hydraulic pump normal	Yes
-----------------------------	-----

## BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★☆☆
Brake pedal	★★★★★

## TRANSMISSION

Transmission controls	★★★★★
Transmission noisy	No
Leaks	No
Transmission oil level ok	Yes
Transmission fully operational in all gears forward and reverse	Yes

## DRIVE CHAIN/TANDEMS

Differential lock/unlock working	Yes
Tandem housing	★★★★★
Left tandem leaking	No
Left tandem oil level ok	Yes
Right tandem leaking	No
Right tandem oil level ok	Yes
Wheel bolts and rims	★★★★★

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Head lights working	Yes
Tail lights working	Yes
Signal lights working	Yes

## SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking Brake	Working

**TYRES**

**FRONT LEFT TYRES**

Percentage life remaining 30%

**MIDDLE LEFT TYRES**

Percentage life remaining 40%

**REAR LEFT TYRES**

Percentage life remaining 40%

**REAR RIGHT TYRES**

Percentage life remaining 40%

**MIDDLE RIGHT TYRES**

Percentage life remaining 40%

**FRONT RIGHT TYRES**

Percentage life remaining 30%

New/Excellent  
★★★★★

Very good  
★★★★☆

Good  
★★★☆☆

Fair  
★★★☆☆

Poor  
★★☆☆☆

