

CATERPILLAR 330D L

Description

Caterpillar 330L E, Engine brand and model Caterpillar C9DI, 200kW, CE, Air conditioning, Central lubrication, Width of the pads 600mm, Mono boom, Length of the mono boom 6.50m, Length of the stick 3.20m, New digging bucket with teeth, Width of the bucket 1.40m, Piped for hammer, shear and clamp, Burst valve on lift cylinder, Hours certified by Caterpillar, In good and clean condition.



Year	2007
Hours	8909
Weight	37.500 kg
Serial number	CAT0330DCRAS00916
Reference	209663

[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★Very good
★★★★☆Good
★★★★☆Fair
★★☆☆☆Poor
★☆☆☆☆

INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar C9DI
Engine power in kW	200kW
CE	✓
Air conditioning	✓
Width of the pads	600mm
Boom	Mono boom
Length of the mono boom	6.50m
Length of the stick	3.20m
Bucket	New digging bucket with teeth
Width of the bucket	1.40m
Piped	Piped for hammer, shear and clamp
Hours	Hours certified by Caterpillar
Overall condition	In good and clean condition.

DOCUMENTS

CE document	CE document available
Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Bottom plates	★★★★☆
Counter weight	★★★★☆
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★☆
Cabin	★★★★☆
Pre-cleaner bowl	★★★★☆

Cracks or welds	No
-----------------	----

ENGINE DETAILS AND CONDITION

Engine number	THY03686
Arrangement number	224-9843
Air cleaner	New
Anti-freeze level °C	-35°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★★
Radiator	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	50%
Chains	50%
Bushings	60%

Sprockets	70%
Idlers	70%
Bottom rollers	60%
Top rollers	70%
Track pads	30%

SAFETY ITEMS

Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Heater	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No warnings available
Mirrors	Small crack, no need to repair
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
--------------------	-------

Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Additional work lights working	Few lights don't work

