


INSPECTION REPORT

CATERPILLAR 950H

The Caterpillar 950H is a robust and efficient wheel loader, powered by a Caterpillar C7 engine that delivers 146 kW, ensuring high performance and reliability. This 2008 model features a well-maintained, spacious EROPS cabin for operator comfort and safety. It's equipped with a GP bucket with a bolt-on edge, measuring 3.00m in width, for versatile material handling. The machine is fitted with 23.5R25 tires and boasts a complete steering wheel, ride control, and autoshift for ease of operation. Certified by Caterpillar, it records 11,116 operating hours and is documented to be in good and clean condition, ready for immediate work.



Specifications

Year	2008
Hours	11116
Weight	18.500 kg
Serial number	CAT0950HTN1A01868
Reference	213699

Features

Engine and model	Caterpillar C7
Engine power	146 kW
CE	✓
Erops cabin	✓
Tyre size	23.5R25
Bucket	GP bucket with bolt on edge
Width of the bucket	3.00m
Steering	Complete steering wheel
Ride control	✓
Autoshift	✓
Hours	Hours certified by Caterpillar
Overall condition	In good and clean condition.

Documents

CE document	CE document available
Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★

Engine Details And Condition

Engine number	C7C09335
Air cleaner	Clean
Anti-freeze level °C	-49°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

Operator Station

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Not working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Small crack no need to repair
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

Bucket

Overall condition of the bucket	★ ★ ★ ★ ★
Bottom	★ ★ ★ ★ ★
Sides	★ ★ ★ ★ ★
Cutting edge	★ ★ ★ ★ ★

Frame

Play articulation point	★ ★ ★ ★ ★
Play loading frame	★ ★ ★ ★ ★
Play bucket pins	★ ★ ★ ★ ★

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★ ★ ★ ★ ★
Hydraulic tank/sight glass and cap	★ ★ ★ ★ ★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★ ★ ★ ★ ★

Brake

Service brake operation	★ ★ ★ ★ ★
Parking brake operation	★ ★ ★ ★ ★
Compressor	★ ★ ★ ★ ★

Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★ ★ ★ ★ ★
Batteries	★ ★ ★ ★ ★
Starter	★ ★ ★ ★ ★
Cabin lights working	Few lights don't work
Tail lights working	Yes
Additional work lights working	Few lights don't work

Safety Items

Backup alarm	Not working
Seat belt	Available
Horn	Working

Tyres

Front Left

Percentage life remaining 40%

Rear Left

Percentage life remaining 40%

Rear Right

Percentage life remaining 40%

Front Right

Percentage life remaining 40%



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)



sales@smitma.com



[+31 \(0\) 77 3999 840](tel:+31(0)773999840)