


CATERPILLAR 432F2

Description

Caterpillar 432F2, Engine Caterpillar, C4.4, 74.5 kW, EPA, CE, Air conditioning, Erops cabin, 480/80-26 + 335/80-20, 4/1 bucket, Hydraulic quick release rear, Width of the loader bucket 2.40m, Width of the backhoe bucket 0.35m, Width of the additional bucket(s) 0.90m Teeth bucket+ 1.50m Ditch cleaning bucket, 3th valve, Complete steering wheel, Autoshift, Beacon, 2 stabilizers, Turbo, Power shift, Servo control, Ride control, Extended hoe, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year	2017
Hours	2659
Weight	9030 kg
Serial number	CAT0432FLHWP01502
Reference	209523

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine	Caterpillar
Engine model	C4.4
Engine power	74.5 kW
EPA	✓
CE	✓
Backhoe bucket	Digging bucket with teeth

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	W7N31589
Arrangement number	4365177
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-38°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★

Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

FRONT BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★
Sides	★★★★★

REAR BUCKET

Overall condition of the bucket	★★★★★
Sides	★★★★★

Teeth	★★★★★
FRAME	
Play loading frame	★★★★★
Play bucket pins	★★★★★
Cracks or welds	No
HYDRAULICS	
Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★
BRAKE	
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
DRIVE TRAIN/TRANSMISSION	
Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level front right final drive ok	Yes
Drivetrain leaks	No
ELECTRICAL, STARTING AND CHARGING SYSTEM	
Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes

Additional work lights working

Yes

SAFETY ITEMS

Seat belt

Available

Horn

Working

Beacon

Working

TYRES

FRONT LEFT

Tread dept in mm

19mm

REAR LEFT

Tread dept in mm

11mm

REAR RIGHT

Tread dept in mm

10mm

FRONT RIGHT

Tread dept in mm

17mm

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

