

Evaluation Wheel Excavator		www.mevas.net	 MEVAS			
Customer/Location:	Prima / Hardenberg	vers 12-2024				
Date:	16.12.2025					
Machine / type:	Hyundai HW140	Hour reading:	11432			
Serial No.:	HHKHK402PG0000008	Year:	2016			
Inspector:	B. Hecker	stick length:	2,50 m			
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/>	A/C <input checked="" type="checkbox"/> stick check valve <input checked="" type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	quick coupler <input type="checkbox"/> DPF <input checked="" type="checkbox"/>			
mono-boom <input type="checkbox"/>	boom variable <input checked="" type="checkbox"/>	hammer lines <input checked="" type="checkbox"/>	lines for grapple / shear <input checked="" type="checkbox"/>			
cab		cab door	good			
seat, arm rests	good	windows & mirrors	good			
switches, levers	1)	wipers, washer	good			
gauges & warn lights	reverse cam not working	floor mat & pedals	good			
aircon / heater	good	cab structure	good			
engine						
leaks & seals	no leaks seen	Serial No.	22187428			
oil condition & level	good	cooling system	cooler compartment dirty			
exhaust, muffler	good	blow by	minor			
smoke	normal	belts & filters	good			
DPF/DEF status	good	coolant condition	good			
visual inspection exterior		counterweight	good			
chassis & carbody	good	bumpers & covers	minor dents			
side doors	good	outriggers & blade	2)			
stairs, hand rails	good	lights, batteries	good			
boom	good	paintwork	good			
stick	good	rims, wheel nuts	good			
hydraulics & drive train		boom cylinders	good			
hoses & lines	good	stick cylinder	good			
pump & valve bloc	good	bucket cylinder	good			
transmission gear	good	outr/blade cylinders	good			
axles	good	universal joints	good			
swivel joint	good					
functional test		suspension lock	good			
pins boom	minor play	pump noises	normal			
pins stick	minor play	slew ring play	1,5 mm Spiel			
pins bucket	minor play	brake & park brake	good			
boom self drift	good	electric system	good			
swing drive/brake	good	drive operation	good			
tools		additional bucket	no			
bucket dimension	1,2m GP bucket	coupler brand	no			
bucket condition	new	coupler condition	no			
tires	mm (%) remaining life	size:	10.00 - 20			
front right	40%	twin / mono:	twin			
front left	40%	spacer rings:				
rear right	40%	damages or cuts:	<input checked="" type="checkbox"/>			
rear left	40%	solid:	<input type="checkbox"/>			
problems, details:						
1) deadmans lever disengage knob missing						
2) hitch pin attached to leveling blade						
<p><i>The machine is in general good condition. Scheduled maintainance and cleaning of cooler compartment recommended.</i></p>						
<p>dimensions for transport: 3,00 m x 2,50 m x 3,20 m</p>						
<p>© 2024 MEVAS. Liability for hidden defects excluded. Terms/Conditions: www.mevas.net/legal-documents/imprint</p>						