


INSPECTION REPORT

KOMATSU WA470-8 - Joystick Steering

The Komatsu WA470-8 wheel loader, manufactured in Japan in 2018, is equipped with a 204kW Komatsu SAA6D125E-7 engine. It features an Erops cabin, air conditioning, a central lubrication system, and a GP bucket with teeth measuring 3.10m wide. With genuine hours of operation, it includes enhanced safety and operational features such as a backup camera, alarm, AM/FM radio, and Autoshift functionality. This wheel loader is in very good and clean condition, weighs 26,750 kg, and offers a spacious interior with modern amenities.



Specifications

Year	2018
Hours	11848
Weight	26.750 kg
Serial number	KMTWA129VJHH55330
Reference	213928

Features

Engine and model	Komatsu SAA6D125E-7
Engine power	204kW
CE	✓
Erops cabin	✓
Tyre size	26.5R25
Bucket	GP bucket with teeth
Width of the bucket	3.10m
Steering	Complete steering wheel
Autoshift	✓
Central lubrication	Central lubrication working
Hours	Genuine hours
Overall condition	In very good and clean condition.

Documents

Parts book	✓
Operation manual	✓

General Appearance

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Toolbox	★★★★★
Central greasing working	Yes

Engine Details And Condition

Engine number	863413
Air cleaner	Clean
Anti-freeze level °C	-39°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

Operator Station

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

Bucket

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

Frame

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

Hydraulics

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

Brake

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

Drive Train/ Transmission

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Drivetrain leaks	No

Electrical, Starting And Charging System

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

Safety Items

Backup alarm	Working
Seat belt	Available
Horn	Working

Tyres

Front Left

Tread dept in mm	23mm
Percentage life remaining	30%
Retreaded	Yes

Rear Left

Tread dept in mm	5mm
Percentage life remaining	5%
Retreaded	Yes

Rear Right

Tread dept in mm	9mm
Percentage life remaining	10%
Retreaded	Yes

Front Right

Tread dept in mm	11mm
Percentage life remaining	10%
Retreaded	Yes



+31 (0) 77 3999 840



sales@smitma.com



+31 (0) 77 3999 840