

INSPECTION REPORT

DYNAPAC CC1300

The DYNAPAC CC1300 is a powerful 2018 model vibrating roller, equipped with a reliable Kubota V2203 engine providing 33.3kW of power. With a drum width of 1.30 meters, this machine ensures efficient compaction. Features include a water sprinkler system, drum drive, vibrating drums, backup alarm, and a beacon. The machine is in excellent, clean condition, with genuine hours of 1143 and CE certification. Manufactured in Sweden, it weighs 3915 kg and measures 2.80 x 1.46 x 1.90m.



Specifications

| | |
|---------------|-------------------|
| Year | 2018 |
| Hours | 1143 |
| Weight | 3915 |
| Serial number | 10000334LJA021567 |
| Reference | 212942 |

Features

| | |
|--------------------|--------|
| Engine brand | Kubota |
| Engine model | V2203 |
| Engine power in kW | 33.3kW |
| CE | ✓ |

Documents

| | |
|------------------|---|
| Parts book | ✓ |
| Operation manual | ✓ |

General Appearance

| | |
|-----------------------------|-------|
| Serial number plate checked | Yes |
| Paint | ★★★★☆ |
| Decals | ★★★★☆ |
| Bonnet | ★★★★☆ |
| Chassis | ★★★★☆ |
| Steps/ladders | ★★★★☆ |

Engine Details And Condition

| | |
|-----------------------------|---------|
| Engine number | 7HC5462 |
| Air cleaner | Clean |
| Anti-freeze level °C | -26°C |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★★ |
| Muffler | ★★★★★ |
| Exhaust stack | ★★★★★ |
| Hoses | ★★★★★ |
| Good cold start | Yes |
| Engine power | ★★★★★ |
| Blow by | ★★★★★ |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | ★★★★★ |
| Fan | ★★★★★ |
| Radiator | ★★★★★ |

Safety Items

| | |
|---------------|-----------|
| Backup alarm | Working |
| Seat belt | Available |
| Horn | Working |
| Parking brake | Working |
| Beacon | Working |

Operator Station

| | |
|-------------|-----------------------|
| Hourmeter | Working |
| Gauges | Working |
| Switches | ★★★★★ |
| Display | ★★★★★ |
| Warning | No Warnings Available |
| Cabin floor | ★★★★★ |
| Seat | ★★★★★ |

Front Drum

| | |
|---------------------|-------|
| Vibratory system | ★★★★★ |
| Drum surface | ★★★★★ |
| Rubber mounts | ★★★★★ |
| Drum scrapers | ★★★★★ |
| Travel motors | ★★★★★ |
| Drum measured in mm | 14mm |

Rear Drum

| | |
|---------------------|-------|
| Vibratory system | ★★★★★ |
| Drum surface | ★★★★★ |
| Rubber mounts | ★★★★★ |
| Drum scrapers | ★★★★★ |
| Travel motors | ★★★★★ |
| Drum measured in mm | 14mm |

Steering

| | |
|----------------------------|-------|
| Play articulating point | ★★★★★ |
| Steering cylinders leaking | No |
| Play steering cylinders | ★★★★★ |

Hydraulics


| | |
|------------------------------------|-------|
| Hydraulic oil level ok | Yes |
| Hydraulic lines and fittings | ★★★★★ |
| Hydraulic tank/sight glass and cap | ★★★★★ |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★★ |

Electrical, Starting And Charging System

| | |
|------------------------|-------|
| Alternator functioning | Yes |
| Wiring | ★★★★★ |
| Batteries | ★★★★★ |
| Starter | ★★★★★ |

 [+31 \(0\) 77 3999 840](tel:+31(0)773999840)

 sales@smitma.com

 [+31 \(0\) 77 3999 840](tel:+31(0)773999840)