

CATERPILLAR 330D L

Description

Caterpillar 330DL, Engine brand and model Caterpillar C9, Air conditioning, Width of the pads 800mm, Mono boom, Length of the mono boom 6.50m, Length of the stick 3.20m, Digging bucket with teeth, Width of the bucket 1.52m, Hours certified by Caterpillar, In good and clean condition.



Year	2008
Hours	10480
Weight	35300 kg
Serial number	CAT0330DEMWP03302
Reference	208167

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆


INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar C9
Air conditioning	✓
Width of the pads	800mm
Boom	Mono boom
Length of the mono boom	6.50m
Length of the stick	3.20m
Bucket	Digging bucket with teeth
Width of the bucket	1.52m
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Body work	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Engine cover doors	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Bottom plates	★ ★ ★ ★ ★
Counter weight	★ ★ ★ ★ ★
Toolbox	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	THX18276
Arrangement number	280-1098
Air cleaner	Clean

Anti-freeze level °C	-27
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	60%
Chains	70%
Bushings	70%
Sprockets	70%
Idlers	60%
Bottom rollers	30%
Top rollers	90%
Track pads	50%

SAFETY ITEMS

Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Few don't work
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Not Working
Interior lights	Not Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	High speed doesn't work
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★

Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★

New/Excellent ★★★★★	Very good ★★★★★	Good ★★★★★	Fair ★★★★★	Poor ★★★★★
------------------------	--------------------	---------------	---------------	---------------

Copyright Smitma BV

