

CATERPILLAR 730

Description

Caterpillar 730, Engine Caterpillar , C11, 239 kW, CE, Air conditioning, 6x6, Erops cabin, 750/65R25 Michelin, Retarder, Heated body, Big tailgate, Backup camera, Backup alarm, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year	2008
Hours	7333
Weight	22850 kg
Serial number	CAT00730CB1M02100
Reference	209850

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆


INSPECTION REPORT

FEATURES

Engine	Caterpillar
Engine model	C11
Engine power	239 kW
CE	✓
Air conditioning	✓
Configuration	6x6
Erops cabin	✓
Retarder	✓
Heated body	✓
Tailgate	Big tailgate
Backup camera	✓
Backup alarm	✓
Hours	Hours certified by Caterpillar
Overall condition	In very good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Decals	★★★★☆☆
Bonnet	★★★★☆☆
Chassis	★★★★☆☆
Steps/ladders	★★★★☆☆
Grab irons	★★★★☆☆
Cabin	★★★★☆☆
Transmission guard	★★★★☆☆

ENGINE DETAILS AND CONDITION

Engine number	RSX11145
Arrangement number	292-9283
Air cleaner	Clean

Anti-freeze level °C	-38°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Total kilometers	33672 km
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Small crack no need to repair
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

Door lock	Working
FRAME	
Play front suspension frame	★★★★★
Play middle suspension frame	★★★★★
Play rear suspension frame	★★★★★
Play articulation point	★★★★★
Shock absorbers articulation point	★★★★★
Play body tipping pin	★★★★★
Bearings tipping cylinders	★★★★★
Shock absorbers body	★★★★★
Play rear equalizer	★★★★★
Shock absorbers equalizer	★★★★★
Cracks or welds	No
BODY	
Condition outside body	★★★★★
Body plates	★★★★★
Body heating system	★★★★★
Condition tailgate	★★★★★
Cracks or welds	No
HYDRAULICS	
Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★
BRAKE	
Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★
Brake pedal	★★★★★
DRIVE TRAIN/TRANSMISSION	
Transmission fully operational in all gears forward and reverse	Yes

Transmission oil level ok	Yes
Transfer gear box oil level ok	Yes
Transmission noisy	No
Differential lock/unlock working	Yes
Oil level front axle ok	Yes
Oil level middle axle ok	Yes
Oil level rear axle ok	Yes
Oil level front left final drive ok	Yes
Oil level middle left final drive ok	Yes
Oil level rear left final drive ok	Yes
Oil level rear right final drive ok	Yes
Oil level middle right final drive ok	Yes
Oil level front right final drive ok	Yes
Drive chain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Backup camera	Working
Seat belt	Available
Horn	Working

TYRES

FRONT LEFT	
Tread dept in mm	29mm
MIDDLE LEFT	
Tread dept in mm	12mm
REAR LEFT	
Tread dept in mm	14mm

REAR RIGHT

Tread dept in mm 20mm

MIDDLE RIGHT

Tread dept in mm 12mm

FRONT RIGHT

Tread dept in mm 21mm

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------

Copyright Smitma BV

