

CATERPILLAR 323D LN

Description

Caterpillar 323D LN , Engine brand and model Caterpillar C6.4, Air conditioning, Width of the pads 500mm, Mono boom, Length of the mono boom 5.70m, Length of the stick 2.50m, New digging bucket with teeth, Width of the bucket 1.40m, Piped for hammer, Hours certified by Caterpillar, In good and clean condition.



Year	2007
Hours	13194
Weight	13000 kg
Serial number	CAT0323DCRAC00299
Reference	208752

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar C6.4
Air conditioning	✓
Width of the pads	500mm
Boom	Mono boom
Length of the mono boom	5.70m
Length of the stick	2.50m
Bucket	New digging bucket with teeth
Width of the bucket	1.40m
Piped	Piped for hammer
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★☆☆
Chassis	★★★★★
Bottom plates	★★★★★
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★☆☆
Grab irons	★★★★★
Cabin	★★★★★
Cracks or welds	Yes
Note: Stick	

ENGINE DETAILS AND CONDITION

Engine number	GDC02947
---------------	----------

Arrangement number	279-7865
Air cleaner	Clean
Anti-freeze level °C	-41°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	50%
Chains	50%
Bushings	50%
Sprockets	60%
Idlers	50%
Bottom rollers	40%
Top rollers	80%

Track pads	30%
SAFETY ITEMS	
Seat belt	Available
Horn	Not Working
OPERATOR STATION	
Hourmeter	Working
Air conditioning	Working
Heater	Not Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Small crack, no need to repair
Windshield wipers	Not Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working
HYDRAULICS	
Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★
BOOM AND STICK	
Play lift cylinder	★★★★★
Lift cylinders leaking	No

Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Additional work lights working	Yes

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

