

CATERPILLAR CS76 XT

Description

Caterpillar CS76 XT, Caterpillar , C6.6, 129.5 kW, CE, Erops cabin, 23.1-26, Frequency meter, Backup camera, Backup alarm, Hours certified by Caterpillar, In very good and clean condition.



Year	2011
Hours	4883
Weight	18.800 kg
Serial number	CAT0CS76CCYX00633
Reference	210009

[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★Very good
★★★★★Good
★★★★★Fair
★★★★★Poor
★★★★★

INSPECTION REPORT

FEATURES

Engine brand	Caterpillar
Engine model	C6.6
Engine power in kW	129.5 kW
CE	✓
Tyre size	23.1-26
Hours	Hours certified by Caterpillar
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Steps/ladders	★★★★☆
Cabin	★★★★☆

ENGINE DETAILS AND CONDITION

Engine number	C6E34108
Air cleaner	New
Anti-freeze level °C	-39°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★☆
Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆

Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Not Working
Backup camera	Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Not Working
Gauges	Working
Switches	★★★★★
Warnings	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Leakages	No

Drum oil level ok Yes

Vibration High and low vibration frequency working

STEERING

Articulate cylinder leaking No

Play articulate cylinder 

Play articulating point 

HYDRAULICS

Hydraulic oil level ok Yes

Hydraulic lines and fittings 

Hydraulic tank/sight glass and cap 

Noise hydraulic pump normal Yes

Operating condition hydraulics 

DRIVE CHAIN

Rear axle leakages No

Wheel bolts and rims 

Travel motors 

Oil level left final drive ok Yes

Left final drive leaking No

Oil level right final drive ok Yes

Right final drive leaking No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning Yes

Wiring 

Batteries 

Starter 

Cabin lights working Few lights don't work

Additional work lights working Yes

TYRES

REAR LEFT TYRES

Tread dept in mm 19mm

Percentage life remaining 70%

REAR RIGHT TYRES

Tread dept in mm 20mm

Percentage life remaining

70%

