

CATERPILLAR M318F

Description

Caterpillar M318F, Engine brand Caterpillar, C7.1, 129.4kW, EPA, CE, Air conditioning, Central lubrication, Backup camera, Beacon, Cat walk, Tyre size 650/45-22.5, V/A boom, Length of the stick 2.60m, Hydraulic quick release, Ditch cleaning bucket, Width of the bucket 1.99m, Piped for hammer & shear, Burst valve on lift, V/A and stick cylinder, Hours certified by Caterpillar, In good and very clean condition.



Year	2017
Hours	11638
Weight	17.700 kg
Serial number	CATM318FEFB800277
Reference	209078

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★☆☆

Copyright Smitma BV



INSPECTION REPORT

FEATURES

Engine brand	Caterpillar
Engine Model	C7.1
Engine power in kW	129.4kW
EPA	✓
CE	✓
Air conditioning	✓
Tyre size	650/45-22.5
Boom	V/A boom
Bucket	Ditch cleaning bucket
Width of the bucket	1.99m
Piped	Piped for hammer & shear
Burst valve	Burst valve on lift, V/A and stick cylinder
Overall condition	In good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Counter weight	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	D8T20606
Arrangement number	4922233
EPA sticker available	Yes
Air cleaner	New
Anti-freeze level °C	-36°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★

SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working
Beacon	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Note: Play on the boom pen	
Play V/A boom pins	★★★★★
Play V/A cylinder	★★★★★
V/A cylinder leaking	No
Play stick cylinder	★★★★★
Stick cylinder leaking	No

Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition V/A boom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work
Tail lights working	Yes
Additional lights working	Yes

TYRES

FRONT LEFT	
Tread dept in mm	13mm
REAR LEFT	
Tread dept in mm	14mm
REAR RIGHT	
Tread dept in mm	14mm
FRONT RIGHT	
Tread dept in mm	10mm

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------

Copyright Smilma BV

