

WIRTGEN W150

Description

Wirtgen W150, Cummins, QSL, 261kW, EPA, CE, Width of the milling drum 1,50m, Milling depth 300mm, Standard milling drum, Foldable conveyor belt, 2 slope & 1 grade control, Hydraulic lifting receiving conveyor, Hydraulic lifting side plates, Hydraulic canopy, Anti slip control, Backup alarm, Genuine hours, Small welding on the frame, In good and clean condition.



Year	2009
Hours	10228
Weight	19.950 kg
Serial number	05130070
Reference	210699

[Download photos](#)

CONTACT US:

SALES@SMITMA.COM

+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★★☆

Fair
★★☆☆☆

Poor
★☆☆☆☆



INSPECTION REPORT

FEATURES

Engine brand	Cummins
Engine model	QSL
Engine power in kW	261kW
EPA	✓
CE	✓
Width of the milling drum	1,50m
Milling depth	300mm
Type of milling drum	Standard milling drum
Conveyor belt	Foldable conveyor belt
Hydraulic lifting receiving conveyor	✓
Hydraulic lifting side plates	✓
Backup alarm	✓
Hours	Genuine hours
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★☆
Cabin	★★★★☆
Pre-cleaner bowl	★★★★☆

ENGINE DETAILS AND CONDITION

Engine number	21894466
EPA sticker available	Yes
Air cleaner	New

Anti-freeze level °C	-25°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	Not Major
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

WATERPUMP

Waterpump working	Yes
-------------------	-----

OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No Warnings Available
Seat	★★★★★

POWER BELT

Power belt	★★★★★
Tensioner	★★★★★
Pulleys	★★★★★

DRUM

Toolholders	★★★★★
Picks	★★★★★
Scrapers	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Additional work lights working	Few lights don't work

SAFETY ITEMS

Backup alarm	Working
Horn	Working

UNDERCARRIAGE

FRONT LEFT	
Overall condition	70%
Chains	70%
Bushings	70%
Sprockets	80%
Idlers	70%
Bottom rollers	70%
Track pads	70%

REAR LEFT

Overall condition	70%
Chains	70%
Bushings	70%

Sprockets	80%
Idlers	70%
Bottom rollers	70%
Track pads	70%
REAR RIGHT	
Overall condition	70%
Chains	80%
Bushings	80%
Sprockets	80%
Idlers	70%
Track pads	70%
FRONT RIGHT	
Overall condition	60%
Chains	80%
Bushings	80%
Sprockets	80%
Idlers	70%
Bottom rollers	80%
Track pads	30%
CONVEYOR BELT	
<hr/>	
SMALL CONVEYOR	
Belt	
Frame	
Rollers	
<hr/>	
LARGE CONVEYOR	
Belt	
Frame	
Rollers	

