

AMMANN ARX45

Description

Ammann ARX45, Yanmar , 4TNV88-BPAMM, 29.6 kW, Width of the drum 1.38m, EPA, CE, Erops cabin, Water sprinkler system, Drum drive, Both drum vibrating, Backup alarm, Beacon, In good and clean condition.



Year	2017
Hours	934
Weight	4650 kg
Serial number	6180209
Reference	211960

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Yanmar
Engine model	4TNV88-BPAMM
Engine power in kW	29.6 kW
EPA	✓
CE	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Decals	★★★★☆☆
Bonnet	★★★★☆☆
Steps/ladders	★★★★☆☆

ENGINE DETAILS AND CONDITION

Engine number	100543
EPA sticker available	Yes
Air cleaner	New
Anti-freeze level °C	-46°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No

Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

SAFETY ITEMS

Backup alarm	Not Working
Seat belt	Available
Horn	Working
Parking brake	Working
Beacon	Working

OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No Warnings Available
Cabin floor	★★★★☆
Seat	★★★★☆

FRONT DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Travel motors	★★★★☆
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

REAR DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆

Drum scrapers	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

STEERING

Play articulating point	★★★★★
Steering cylinders leaking	No
Play steering cylinders	★★★★★
Note: Little play	

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

