

BOMAG BW213D-5

Description

Bomag BW213D-5, Deutz, TCD 3.6 L4, 95kW, CE, Erops cabin, 23.1-26, Speed meter, Air conditioning, Backup alarm, Beacon, AM/FM radio, Genuine hours, In very good and very clean condition.



Year	2019
Hours	4708
Weight	12.510 kg
Serial number	101586151481
Reference	210857

[Download photos](#)

CONTACT US:

SALES@SMITMA.COM

+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★



INSPECTION REPORT

FEATURES

Engine brand	Deutz
Engine model	TCD 3.6 L4
Engine power in kW	95kW
CE	✓
Tyre size	23.1-26
Speed meter	✓
Beacon	✓
Hours	Genuine hours
Overall condition	In very good and very clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Air cleaner	Clean
Anti-freeze level °C	-41°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★

Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working
Beacon	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

DRUM

Vibratory system	★★★★★
Drum surface	★★★★★

Rubber mounts	★★★★★
Drum scrapers	★★★★★
Leakages	No
Drum oil level ok	Yes
Vibration	High and low vibration frequency working
Drum measured in mm	27mm

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

DRIVE CHAIN

Oil level rear axle ok	Yes
Rear axle leakages	No
Wheel bolts and rims	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Additional work lights working	Yes

TYRES

REAR LEFT TYRES

Tread dept in mm 20

Percentage life remaining 70%

Retreaded No

REAR RIGHT TYRES

Tread dept in mm 22

Percentage life remaining 70%

Retreaded No

New/Excellent
★★★★★

Very good
★★★★★ ★

Good
★★★★★ ★★

Fair
★★★ ★★

Poor
★ ★ ★ ★



Copyright Smitma BV