

BOMAG BW213D-5

Description

Bomag BW 213 D-5, Deutz, TCD 3.6 L4, 95 kW, EPA, CE, Erops cabin, 23.1-26, Speed meter, Air conditioning, Backup alarm, In very good and very clean condition.



| | |
|---------------|--------------|
| Year | 2019 |
| Hours | 4843 |
| Weight | 12.510 kg |
| Serial number | 101586151491 |
| Reference | 210856 |

[Download photos](#)

CONTACT US:

SALES@SMITMA.COM

+31(0)773999840

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★



INSPECTION REPORT

FEATURES

| | |
|--------------------|--|
| Engine brand | Deutz |
| Engine model | TCD 3.6 L4 |
| Engine power in kW | 95 kW |
| EPA | ✓ |
| CE | ✓ |
| Tyre size | 23.1-26 |
| Speed meter | ✓ |
| Overall condition | In very good and very clean condition. |

DOCUMENTS

| | |
|------------------|---|
| Parts book | ✓ |
| Operation manual | ✓ |

GENERAL APPEARANCE

| | |
|-------------------------------|-------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★★★★★ |
| Decals | ★★★★★ |
| Bonnet | ★★★★★ |
| Chassis | ★★★★★ |
| Steps/ladders | ★★★★★ |
| Cabin | ★★★★★ |

ENGINE DETAILS AND CONDITION

| | |
|--------------------------|----------|
| Engine number | 12312037 |
| EPA sticker available | Yes |
| Air cleaner | Clean |
| Anti-freeze level °C | -44°C |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★★ |
| Muffler | ★★★★★ |
| Exhaust stack | ★★★★★ |

| | |
|-----------------------------|--------|
| Hoses | |
| Good cold start | Yes |
| Engine power | |
| Blow by | |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | |
| Fan | |
| Radiator | |

SAFETY ITEMS

| | |
|---------------|-----------|
| Backup alarm | Working |
| Seat belt | Available |
| Horn | Working |
| Parking brake | Working |

OPERATOR STATION

| | |
|-------------------|-----------------------|
| Hourmeter | Working |
| Air conditioning | Working |
| Heater | Working |
| Gauges | Working |
| Switches | |
| Display | |
| Warnings | No warnings available |
| Mirrors | Not broken |
| Cabin glass | Not broken |
| Windshield wipers | Working |
| Interior lights | Working |
| Cabin floor | |
| Interior roof | |
| Seat | |
| Door lock | Working |

DRUM

| | |
|------------------|--|
| Vibratory system | |
|------------------|--|

| | |
|-------------------|--|
| Drum surface | ★★★★★ |
| Rubber mounts | ★★★★★ |
| Drum scrapers | ★★★★★ |
| Leakages | No |
| Drum oil level ok | Yes |
| Vibration | High and low vibration frequency working |

STEERING

| | |
|-----------------------------|-------|
| Articulate cylinder leaking | No |
| Play articulate cylinder | ★★★★★ |
| Play articulating point | ★★★★★ |

HYDRAULICS

| | |
|------------------------------------|-------|
| Hydraulic oil level ok | Yes |
| Hydraulic lines and fittings | ★★★★★ |
| Hydraulic tank/sight glass and cap | ★★★★★ |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★★ |

DRIVE CHAIN

| | |
|--------------------------------|-------|
| Rear axle leakages | No |
| Wheel bolts and rims | ★★★★★ |
| Travel motors | ★★★★★ |
| Oil level left final drive ok | Yes |
| Left final drive leaking | No |
| Oil level right final drive ok | Yes |
| Right final drive leaking | No |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|--------------------------------|-------|
| Alternator functioning | Yes |
| Wiring | ★★★★★ |
| Batteries | ★★★★★ |
| Starter | ★★★★★ |
| Cabin lights working | Yes |
| Additional work lights working | Yes |

TYRES

REAR LEFT TYRES

| | |
|------------------|------|
| Tread dept in mm | 22mm |
|------------------|------|

Percentage life remaining 70%

REAR RIGHT TYRES

Tread dept in mm 22mm

Percentage life remaining 70%

| | | | | |
|---------------|-----------|-------|-------|-------|
| New/Excellent | Very good | Good | Fair | Poor |
| ★★★★★ | ★★★★★ | ★★★★★ | ★★★★★ | ★★★★★ |



Copyright Smitra BV