

CATERPILLAR 318C L

Description

Caterpillar 318C L, Engine brand and model Caterpillar 3066T, Mechanical injection, 94 kW, EPA, CE, Width of the pads 600mm, Mono boom, Length of the mono boom 5.30m, Length of the stick 2.70m, New digging bucket with teeth, Width of the bucket 1.20m, Piped for hammer, Burst valve on lift cylinder, Hours certified by Caterpillar, In good and clean condition.



Year	2004
Hours	10058
Weight	22.400 kg
Serial number	CAT0318CADAH00315
Reference	211095

[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
★★★★★Very good
★★★★★Good
★★★★★Fair
★★★★★Poor
★★★★★

INSPECTION REPORT

FEATURES

Engine brand and model	Caterpillar 3066T
Engine power in kW	94 kW
EPA	EPA
CE	✓
Width of the pads	600mm
Boom	Mono boom
Length of the mono boom	5.30m
Length of the stick	2.70m
Bucket	New digging bucket with teeth
Width of the bucket	1.20m
Piped	Piped for hammer
Hours	Hours certified by Caterpillar
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Bottom plates	★★★★★
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Cracks or welds	Yes

Note: Boom + stick small repairs

ENGINE DETAILS AND CONDITION

Engine number	7JK73515
EPA sticker available	Yes
Air cleaner	New
Anti-freeze level °C	-49°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★★
Engine supports	★★★★☆
Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆

Note: no air conditioning belt

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Teeth	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	40%
Chains	20%
Bushings	10%

Note: 1x bus defect

Sprockets	60%
Idlers	50%
Bottom rollers	30%
Top rollers	30%
Note: 2x defect	
Track pads	60%

SAFETY ITEMS

Seat belt	Available
Horn	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Not Working
Cabin floor	★★★★★
Interior roof	★★★★☆
Seat	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes

Operating condition hydraulics

★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Note: Little play	
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboom	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	No
Additional work lights working	Few lights don't work

New/Excellent
★★★★★

Very good
★★★★★

Good
★★★★★

Fair
★★★★★

Poor
★★★★★

