

Evaluation Wheel Loader		www.mevas.net			
Customer: <i>Prima</i>		vers 12-24			
Date:	17.12.2025				
Machine / type:	<i>Hyundai HL940</i>	location:	<i>Hardenberg</i>		
Serial No.:	<i>HHKHW400VK0000933</i>	Hour reading:	<i>9568</i>		
Inspector:	<i>B. Hecker</i>	Year:			
CE <input type="checkbox"/> A/C <input checked="" type="checkbox"/>	EPA <input checked="" type="checkbox"/> Auto-Greaser <input checked="" type="checkbox"/>	Hydrostat <input type="checkbox"/>	quick coupler <input type="checkbox"/>		
3rd valve <input checked="" type="checkbox"/>	supplemental steering <input checked="" type="checkbox"/>	weigh load <input checked="" type="checkbox"/>	Parts book <input type="checkbox"/> Op-Manual <input type="checkbox"/>		
cab		cab door	<i>good</i>		
seat, arm rests	<i>good</i>	windows, mirrors	<i>good</i>		
switches, levers	<i>good</i>	wipers, washer	<i>good</i>		
gauges & lamps	<i>good</i>	floor mat	<i>good</i>		
aircon / heater	<i>good</i>	cab structure	<i>good</i>		
engine					
leaks & seals	<i>good</i>	Serial No.	<i>22339211</i>		
oil condition & level	<i>good</i>	DPF&DEF status	<i>good</i>		
exhaust, muffler	<i>good</i>	cooling system	<i>good</i>		
smoke	<i>normal</i>	belts & filters	<i>good</i>		
blow by	<i>minor</i>	coolant condition	<i>good</i>		
exterior		counterweight	<i>good</i>		
chassis & lift arm	<i>good</i>	fenders	<i>extensions broken</i>		
engine hood	<i>good</i>	lights, batteries	<i>front lights dull</i>		
stairs, hand rails	<i>good</i>	paintwork	<i>chipped spots</i>		
power train		rims, wheel nuts	<i>good</i>		
axles/differentials	<i>good</i>	universal joints	<i>good</i>		
gearbox	<i>good</i>	transfer gear	<i>good</i>		
power train	<i>good</i>	transm. noises	<i>normal</i>		
hydraulics		steering cylinders	<i>good</i>		
hoses & lines	<i>good</i>	pumps & valves	<i>good</i>		
lift & tilt cylinders	<i>good</i>	steering orbital	<i>good</i>		
functional test	full bucket lift in seconds:		<i>6,4 sec.</i>		
steering	<i>good</i>	articulation play	<i>minor play</i>		
transmission test	<i>good</i>	loader pins	<i>minor play</i>		
stall test	<i>2220->1930->1700rpm</i>	electric system	<i>good</i>		
brake / park brake	<i>good</i>	suppl. steering	<i>good</i>		
bucket		width / capacity	<i>2,60 m</i>		
edges / teeth	<i>good</i>	side condition	<i>good</i>		
bottom	<i>good</i>	quick coupler	<i>N/A</i>		
tires	mm (%) good	size, brand, comments			
front right	<i>50%</i>	<i>20,5 R25 BKT</i>			
front left	<i>50%</i>	<i>20,5 R25 BKT</i>			
rear right	<i>60%</i>	<i>20,5 R25 BKT</i>			
rear left	<i>60%</i>	<i>20,5 R25 BKT</i>			
problems, details:					
The machine is in technical good condition. Smaller repairs recommended.					
Scheduled maintainance recommended.					
transport dimensions L x W x H in meter:		<i>7,00 m x 2,60 m x 3,30 m</i>			