

## BOMAG BW135AD-5

### Description

Bomag BW 135 AD-5, Kubota , V2203-M-ET05, 33.3 kW, Width of the drum 1.29m, EPA, CE, Erops cabin, Water sprinkler system, Drum drive, Both drum vibrating, Cutting edge, Moveable seat, Backup alarm, In very good and very clean condition.



Year	2016
Hours	2654
Weight	3.900 kg
Serial number	101650321317
Reference	208419

[Download photos](#)

### CONTACT US:

[SALES@SMITMA.COM](mailto:SALES@SMITMA.COM)

+31(0)773999840

New/Excellent  
★★★★★

Very good  
★★★★★

Good  
★★★★★

Fair  
★★★★★

Poor  
★★★★★



# INSPECTION REPORT

## FEATURES

Engine brand	Kubota
Engine model	V2203-M-ET05
Engine power in kW	33.3 kW
EPA	✓
CE	✓

## DOCUMENTS

Parts book	✓
Operation manual	✓

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Chassis	★★★★★
Steps/ladders	★★★★★

## ENGINE DETAILS AND CONDITION

Engine number	7FF7350
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-46°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★

Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working

## OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★★
Warning	No Warnings Available
Seat	★★★★★

## FRONT DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Travel motors	★★★★★
Vibration	High and low vibration frequency working

## REAR DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Vibration	High and low vibration frequency working

## STEERING

Articulate cylinder leaking	No
-----------------------------	----

Play articulate cylinder	★★★★★
Play articulating point	★★★★★

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional lights working	Yes

New/Excellent  
★★★★★

Very good  
★★★★★

Good  
★★★

Fair  
★★

Poor  
★

Copyright Smitma BV

