

BOMAG BW24R

Description

Bomag BW 24 R, Cummins , B4.5-99C, CE, EPA, 11.00-20, Tyre regulation, Erops cabin, Water sprinkler system, Speed meter, Backup camera, Backup alarm, In very good and clean condition.



Year	2005
Hours	3988
Weight	14950 kg
Serial number	201530601551
Reference	210461

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine brand	Cummins
Engine model	B4.5-99C
CE	✓
EPA	✓
Tyre regulation	✓

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★

ENGINE DETAILS AND CONDITION

Engine number	46445360
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-25°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★ ★ ★ ★ ★
Muffler	★ ★ ★ ★ ★
Exhaust stack	★ ★ ★ ★ ★
Hoses	★ ★ ★ ★ ★
Good cold start	Yes
Engine power	★ ★ ★ ★ ★
Blow by	★ ★ ★ ★ ★
Knocking	No

Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆☆
Fan	★★★★☆☆
Radiator	★★★★☆☆

SAFETY ITEMS

Backup alarm	Working
Backup camera	Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★☆☆
Warnings	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆☆
Interior roof	★★★★☆☆
Seat	★★★★☆☆

STEERING

Steering cylinders leaking	No
Play steering cylinders	★★★★☆☆

HYDRAULICS

Hydraulic level ok	Yes
Hydraulic lines and fittings	★★★★☆☆
Hydraulic tank/sight glass and cap	★★★★☆☆
Noise hydraulic pump normal	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning

Yes

Note: NEW!

Wiring

★★★★★★

Batteries

★★★★★★

Starter

★★★★★★

Cabin lights working

Yes

Tail lights

Yes

REAR TYRES**FIRST TYRE**

Percentage life remaining

75%

SECOND TYRE

Percentage life remaining

75%

THIRD TYRE

Percentage life remaining

75%

FOURTH TYRE

Percentage life remaining

75%

New/Excellent



Very good



Good



Fair



Poor

